



LS58ZJX

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF MATCH TDI 105
Colour	Silver
Year of manufacture	2008
Top speed	116 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	132 g/km
CO2 label	E






Internet history

Entry 2

Date	2021-06-13
Pictures	35
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-08
Pictures	35
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-31
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	24
Total items failed	4

MOT #17	2023-08-01 11:10
MOT test number	677642398527
Result	✓ Passed
Next expiry date	2024-07-31
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2022-06-07 13:33
MOT test number	236139169769
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2022-06-06 15:44**MOT test number** 316192353119**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #14** 2021-06-08 10:04**MOT test number** 805322962489**Result** ✓ Passed**MOT #13** 2020-11-11 15:00**MOT test number** 845356059715**Result** ✓ Passed**MOT #12** 2020-11-11 08:44**MOT test number** 361680083793**Result** ✗ Failed**Advice** Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #11**

2019-11-11 10:37

MOT test number

745678379565

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge also aged (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge also aged (5.2.3 (e))
- Advice** Nearside Rear Nail in tyre

MOT #10

2018-11-20 15:10

MOT test number

620123863856

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Tyre worn close to legal limit/worn on edge both rear inner (5.2.3 (e))

MOT #9

2018-11-19 12:49

MOT test number

494661351603

Result

✗ Failed

- Advice** Tyre worn close to legal limit/worn on edge both rear inner (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Central Exhaust system insecure clamp, sleeve (6.1.2 (a))

**MOT #8** 2017-11-07 09:30**MOT test number** 543200675789**Result** ✓ Passed**MOT #7** 2016-11-14 09:25**MOT test number** 157794784495**Result** ✓ Passed**MOT #6** 2015-11-24 12:25**MOT test number** 152200202082**Result** ✓ Passed**MOT #5** 2014-11-25 07:58**MOT test number** 946669224334**Result** ✓ Passed**Notice** Offside rear tyre just passed test,nearside rear perished and both front tyres starting to wear**MOT #4** 2013-11-20 11:48**MOT test number** 746094423348**Result** ✓ Passed**Advice** Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-11-06 12:56**MOT test number** 148061612362**Result** ✓ Passed**Notice** Nearside rear tyre perished**MOT #2** 2011-11-10 15:00**MOT test number** 369454111352**Result** ✓ Passed



MOT #1	2011-11-10 15:00
MOT test number	338554511302
Result	✗ Failed
Pass with rectification	Offside Front Front position lamp(s) not working (1.1.A.3b)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
31 July 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LS58ZJX
Plate since	2019-06-29
Current registration	 LS58ZJX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-11-26
Last registration	2023-08-01
Complete history	See info



Registration #1	2008-11-26	27 mi
Registration #2	2011-11-10	39.309 mi
Registration #3	2012-11-06	46.205 mi
Registration #4	2013-11-20	52.314 mi
Registration #5	2014-11-25	58.160 mi
Registration #6	2015-11-24	63.370 mi
Registration #7	2016-11-14	68.367 mi
Registration #8	2017-11-07	72.991 mi
Registration #9	2018-11-19	76.918 mi
Registration #10	2018-11-20	76.921 mi
Registration #11	2019-11-20	76.921 mi
Registration #12	2020-11-20	76.921 mi
Registration #13	2021-11-20	76.921 mi
Registration #14	2022-11-20	76.921 mi
Registration #15	2023-11-20	76.921 mi
Registration #16	2024-11-20	76.921 mi
Registration #17	2025-11-20	76.921 mi
Registration #18	2026-11-20	76.921 mi
Registration #19	2027-11-20	76.921 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1251 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BXE B29276