





### General information

Make	NISSAN
Model	PULSAR ACENTA DIG-T
Colour	Grey
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption


Power	115 BHP
Max. torque	190 Nm at 2.000 rpm
Engine capacity	1.198 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	С





# Internet history

Entry 1		
Date	2021-08-01	
Pictures	31	
Listing price	View report	



source: autotrader.co.uk



# MOT history

MOT expiry date	2024-08-18
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	10
Total items failed	0

MOT #9		2023-08-02 10:28
MOT test	number	317227122748
Result		✓ Passed
Next expi	ry date	2024-08-18
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))	

MOT #8	2022-08-08 09:53
MOT test number	942599073190
Result	✓ Passed

MOT #7	2021-08-19 07:37
MOT test number	510588336733
Result	✓ Passed

МОТ #6	2021-07-07 14:45
MOT test number	134098721416
Result	🗙 Failed
DANGEROUSNearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))AdviceOffside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



SM65VSP report date: 2024-03-28

MOT #5		2020-11-25 10:05
MOT test I	umber	240592887179
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #4		2019-10-11 14:48
MOT test ı	umber	577551000639
Result		✓ Passed
MOT #3		2018-10-10 09:03
MOT test i	umber	701809403851
Result		✓ Passed
MOT #2		2018-10-10 08:34
MOT test i	umber	814147262214
Result		🗙 Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
DANGER	<b>DUS</b> Nearside Front Tyre tread depth below requirements of 1.6mm also	cut to cord (5.2.3 (e))
MOT #1		2010 10 02 00.55
		2018-10-02 08:55
MOT test I	lunder	404251812654

MOT test r	umber	404251812654
Result		🗙 Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (	5.2.3 (e))
DANGER	<b>DUS</b> Nearside Front Tyre tread depth below requirement	ts of 1.6mm also cut to cord (5.2.3 (e))



Tax & MOT check

	✓ Taxed		✓ МОТ
<b>Tax due:</b> 1 January 2025		Expires: 18 August 2024	
Tax status			Valid until 1 January
Days left			248
MOT expiry date			18 August 2024
Full MOT history			See MOT history
Tax calculation			
Vehicle class		48	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	S.
Category	ame
Туре	

#### Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second	
***********	
********	
**********	
********	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



SM65VSP report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-11-26
Last registration	2023-08-02
Complete history	See info



Registration #1	2015-11-26	13 mi
Registration #2	2018-10-02	11.680 mi
Registration #3	2018-10-10	11.831 mi
Registration #4	2018-10-10	11.831 mi
Registration #5	2019-10-11	22.876 mi
Registration #6	2020-11-25	29.338 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.117 esi





## Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	81%
Pedestrian	75%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1768 mm
Height	1520 mm
Length	4385 mm
Wheel base	2700 mm
Kerb weight	1304 kg
Max. allowed weight	1750 kg
Additional information	
Fuel tank capacity	46
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	136994A