



report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Silver
Year of manufacture	2004
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg
CO2 emission	259 g/km
CO2 label	M







Internet history

Entry 1

Date	2021-11-05
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date 2022-10-20**MOT pass rate** 88 %**MOT passed** 14**Failed MOT tests** 2**Total advice items** 13**Total items failed** 7**MOT #16** 2022-11-16 14:37**MOT test number** 707773553080**Result** ✗ Failed**Minor** Front Position lamp incorrect colour both (4.2.3 (a) (i))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition rear silencers missing (8.1.1 (a))**Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Offside Rear Lower Suspension arm pin or bush excessively worn outer bush (5.3.4 (a) (i))**MOT #15** 2021-10-21 09:56**MOT test number** 757502382261**Result** ✓ Passed**MOT #14** 2019-09-14 07:12**MOT test number** 469872244794**Result** ✓ Passed

**MOT #13** 2018-06-02 11:27**MOT test number** 589770992716**Result** ✓ Passed

- Advice** Radiator damaged.
- Advice** Front lower shock absorber bushes have slight movement.
- Advice** O/S/R lower shock absorber bush has slight play.
- Advice** O/S/R anti roll bar link has play.
- Advice** O/S/R lower suspension arm bush has slight play.

MOT #12 2017-06-10 11:30**MOT test number** 212442746044**Result** ✓ Passed

- Advice** Front lower shock absorber bushes have slight play
- Advice** O/S/R lower suspension arm bush has slight play.
- Advice** O/S/R lower shock absorber bush has slight play.

MOT #11 2016-06-21 08:40**MOT test number** 427748696591**Result** ✓ Passed**MOT #10** 2015-06-10 12:49**MOT test number** 265861665117**Result** ✓ Passed**MOT #9** 2014-05-29 12:28**MOT test number** 437359844153**Result** ✓ Passed

**MOT #8** 2013-06-14 15:00**MOT test number** 998485263136**Result** ✓ Passed**MOT #7** 2013-06-14 11:18**MOT test number** 766805163125**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Nearside Rear Lower Anti-roll bar attachment bracket/mounting insecure (2.4.G.1)**MOT #6** 2012-05-09 12:33**MOT test number** 986650032124**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #5** 2011-05-11 09:22**MOT test number** 955051931138**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #4** 2010-05-11 10:53**MOT test number** 374471330161**Result** ✓ Passed**MOT #3** 2009-05-14 09:18**MOT test number** 481874039167**Result** ✓ Passed



MOT #2	2008-10-21 16:46
MOT test number	623495498224
Result	✓ Passed

MOT #1	2007-10-30 09:16
MOT test number	674063307307
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
31 July 2022

✕
MOT

Expired:
20 October 2022

Tax status	Expired at 31 July 2022
Days left	638 days too late
MOT expiry date	20 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2004-12-07
Last registration	2022-11-16
Complete history	See info



Registration #1	2004-12-07	13 mi
Registration #2	2007-10-30	14.847 mi
Registration #3	2008-10-21	4.786 mi
Registration #4	2009-05-14	6.966 mi
Registration #5	2010-05-11	15.148 mi
Registration #6	2011-05-11	24.217 mi
Registration #7	2012-05-09	33.706 mi
Registration #8	2013-06-14	45.966 mi
Registration #9	2013-06-14	45.968 mi
Registration #10	2013-06-14	45.968 mi
Registration #11	2013-06-14	45.968 mi
Registration #12	2013-06-14	45.968 mi
Registration #13	2013-06-14	45.968 mi
Registration #14	2013-06-14	45.968 mi
Registration #15	2013-06-14	45.968 mi
Registration #16	2013-06-14	45.968 mi
Registration #17	2013-06-14	45.968 mi
Registration #18	2013-06-14	45.968 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	476785357FB