





report date: 2024-03-28

#### General information

Make	PEUGEOT
Model	207 HDI ACTIVE
Colour	Red
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/14



SY12UXM report date: 2024-03-28

# Internet history

#### Entry 1

Date	2021-02-03	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

## **MOT** history

MOT expiry date	2024-07-05
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	37
Total items failed	10

MOT #15	2023-07-06 11:32
MOT test number	424946230446
Result	✓ Passed
Next expiry date	2024-07-05
Advice Rear Direction indicator slightly discoloured both (4.4.3 (a))	
Advice Vehicle structure slightly corroded within 30cm of towbar mounting (6.1.6	(i) (i))
Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))	
Minor Steering rack gaiter damaged or deteriorated, but preventing the ingress of	of dirt (2.1.3 (g) (i))
Advice Seat belt anchorage prescribed area is corroded but not considered exces and have damage (7.1.1 (a) (i))	sive both sills corroded
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	4 (a) (ii))

CarCheck.co.uk page 3/14



report date: 2024-03-28

**MOT #14** 2023-07-06 11:32

**MOT** test number 739126110806

Result × Failed

Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

**Advice** Seat belt anchorage prescribed area is corroded but not considered excessive both sills corroded and have damage (7.1.1 (a) (i))

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) **Advice** 

Advice Rear Direction indicator slightly discoloured both (4.4.3 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Vehicle structure slightly corroded within 30cm of towbar mounting (6.1.6 (i) (i))

**Minor** Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #13** 2022-04-01 10:22

**MOT** test number 481275304060

Result Passed

**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Minor All direction indicators flashing more than 120 times a minute (4.4.4 (a))

**Advice** Parking brake lever has little reserve travel

Minor Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g)

(i))

**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

Minor Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g)

(i))

CarCheck.co.uk page 4/14



report date: 2024-03-28

**MOT #12** 2021-03-25 16:02

**MOT test number** 817818620982

**Result** 
✓ Passed

**MOT #11** 2020-06-12 12:07

**MOT test number** 189367219844

Result 

Passed

MOT #10 2020-06-12 09:48

MOT test number 201685008422

**Result** X Failed

**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #9 2019-05-27 13:40

**MOT test number** 839034852758

**Result** ✓ Passed

MOT #8 2019-05-27 08:42

**MOT test number** 362393004372

**Result** X Failed

**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #7** 2018-05-10 13:57

**MOT test number** 762260967605

**Result** ✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT test number

Fail Offside Front Road wheel badly damaged (4.2.A.1a)

Fail Nearside Headlamp not working on dipped beam (1.7.5a)

MOT #5

MOT test number

658484748952

Result

Advice Offside Rear tyre perished.

Advice N/s & o/s front tyres worn on outer edge close to limit.

**MOT #4** 2017-05-23 08:53 **MOT** test number 840238889921 Result × Failed Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c) Fail Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Offside Rear tyre perished. Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Front Exhaust system not adequately supported (7.1.1) **Advice** N/s & o/s front tyres worn on outer edge close to limit. Fail Nearside Front Mechanical brake component has restricted free movement (3.5.1k)

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT test number

Result

Advice Nearside Rear tyre worn on outer edge.

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2016-05-19 08:49 **MOT** test number 472885242312 Result **X** Failed Offside Headlamp not working on dipped beam (1.7.5a) Fail **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) Fail Direction indicators flashing more than 120 times a minute (1.4.A.2g) **Advice** O/S front and N/S rear tyres worn on edges Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2015-06-03 11:49
MOT test number	649414855169
Result	<b>✓</b> Passed

CarCheck.co.uk page 7/14



SY12UXM report date: 2024-03-28

Tax & MOT check



Tax expired: 30 December 2022



Tax status	Expired at 30 December 2022
Days left	485 days too late
MOT expiry date	5 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates faste since

CarCheck.co.uk page 11/14



SY12UXM report date: 2024-03-28

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

**Contact info** 

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-04-19
Last registration	2023-07-06
Complete history	See info



Registration #1	2012-04-19	11 mi
Registration #2	2015-06-03	23.285 mi
Registration #3	2016-05-19	34.966 mi
Registration #4	2016-05-25	35.228 mi
Registration #5	2017-05-23	44.705 mi
Registration #6	2017-05-23	44.705 mi
Registration #7	2018-05-10	55.756 mi
Registration #8	2018-05-10	55.756 mi
Registration #9	2019-05-27	69.483 mi
Registration #10		11.117 es
Registration #11		11.177 es
Registration #12		11.777 au
Registration #13		11.777 es
Registration #13 Registration #14		11.777 es
		11.777 es 11.777 es 11.777 es
Registration #14		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	see crash video



# Dimensions & weight

Width	1815 mm
Height	1498 mm
Length	4276 mm
Wheel base	2608 mm
Kerb weight	1410 kg
Max. allowed weight	1800 kg

# Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 p.	age 14/14

Number of axles 2

Engine number JBEE0158928