



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 SE
Colour	Silver
Year of manufacture	-
Top speed	134 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	230 Nm at 4.400 rpm
Cylinders	5
Fuel type	Petrol
Consumption city	20.3 mpg
Consumption extra urban	39.8 mpg
Consumption combined	29.4 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-06-25
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-24
Pictures	1
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #18	2022-06-28 15:43
MOT test number	146395477972
Result	✓ Passed
Next expiry date	2023-06-27
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake pad(s) wearing thin outer pad low (1.1.13 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2021-04-06 11:55
MOT test number	683811758584
Result	✓ Passed

MOT #16	2021-04-06 11:55
MOT test number	440240968083
Result	✗ Failed
Pass with rectification	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Pass with rectification	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #15	2020-04-08 10:20
MOT test number	285055531691
Result	✓ Passed

MOT #14	2019-02-23 09:45
MOT test number	387507922708
Result	✓ Passed

MOT #13	2018-03-27 07:43
MOT test number	958939287297
Result	✓ Passed

**MOT #12** 2017-03-16 15:41**MOT test number** 144695684564**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #11 2017-03-15 15:38**MOT test number** 901545615372**Result** ✗ Failed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #10 2016-04-02 10:37**MOT test number** 391306062259**Result** ✓ Passed

**MOT #9** 2015-06-30 11:44**MOT test number** 159141285172**Result** ✓ Passed**MOT #8** 2014-07-22 16:36**MOT test number** 595373704225**Result** ✓ Passed**Notice** Both Rear bumpstop are starting to perish**MOT #7** 2014-07-22 16:36**MOT test number** 188573504201**Result** ✗ Failed**Notice** Both Rear bumpstop are starting to perish**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2013-09-03 09:36**MOT test number** 497546143214**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2012-07-18 17:17**MOT test number** 215490602234**Result** ✓ Passed**Advice** Rear brake juddering slightly (3.7.A.5b)

**MOT #4** 2012-07-17 18:02**MOT test number** 905309992181**Result** ✗ Failed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Fail Front front brake juddering severely (3.7.A.2b)

Advice Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Rear front brake juddering slightly (3.7.A.2b)

MOT #3 2011-07-06 15:02**MOT test number** 716407581171**Result** ✓ Passed**MOT #2** 2010-07-23 12:01**MOT test number** 310654600492**Result** ✓ Passed**MOT #1** 2010-05-24 12:31**MOT test number** 373184940157**Result** ✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SG07LCO
Plate since	2024-03-29
Current registration	SG07LCO
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-06-19
Last registration	2022-06-28
Complete history	See info



Registration #1	2007-06-19	9 mi
Registration #2	2010-05-24	26.646 mi
Registration #3	2010-07-23	27.759 mi
Registration #4	2011-07-06	34.905 mi
Registration #5	2012-07-17	45.474 mi
Registration #6	2012-07-18	45.474 mi
Registration #7	2013-09-03	52.382 mi
Registration #8	2014-07-22	56.518 mi
Registration #9	2015-06-30	62.547 mi
Registration #10	2016-04-02	67.570 mi
Registration #11	2016-05-20	71.577 mi
Registration #12	2016-06-20	75.577 mi
Registration #13	2016-07-20	79.577 mi
Registration #14	2016-08-20	83.577 mi
Registration #15	2016-09-20	87.577 mi
Registration #16	2016-10-20	91.577 mi
Registration #17	2016-11-20	95.577 mi
Registration #18	2016-12-20	99.577 mi
Registration #19	2017-01-20	103.577 mi
Registration #20	2017-02-20	107.577 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1987 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1729 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	4023046