



YFIIVLC

report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER D
Colour	White
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-01-28
Pictures	26
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-20
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	11
Total items failed	8

MOT #16	2023-12-21 12:18
MOT test number	215049078051
Result	✓ Passed
Next expiry date	2024-12-20
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #15	2022-12-20 10:57
MOT test number	460373105311
Result	✓ Passed

MOT #14	2022-02-14 12:42
MOT test number	158453057617
Result	✓ Passed

MOT #13	2022-02-10 14:30
MOT test number	302077878893
Result	✗ Failed
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside rear tyre is cracking

**MOT #12** 2020-11-19 10:05**MOT test number** 836469956596**Result** ✓ Passed**MOT #11** 2019-11-21 10:16**MOT test number** 389496484869**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-11-15 11:39**MOT test number** 106244290121**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #9** 2018-08-02 07:56**MOT test number** 953476571463**Result** ✓ Passed**MOT #8** 2018-01-05 16:09**MOT test number** 999081749820**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)

**MOT #7** 2017-07-31 13:34**MOT test number** 635112167473**Result** ✓ Passed**Advice** Under trays fitted**Advice** Engine covers fitted**MOT #6** 2016-07-22 13:42**MOT test number** 595705519769**Result** ✓ Passed**MOT #5** 2016-07-22 08:09**MOT test number** 493059003096**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2015-06-23 10:51**MOT test number** 189374975115**Result** ✓ Passed**Notice** NSF Tyre Worm on Inner Edge**MOT #3** 2015-06-23 10:51**MOT test number** 725724175112**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** NSF Tyre Worm on Inner Edge



MOT #2	2014-07-17 09:45
MOT test number	218418894140
Result	✓ Passed

MOT #1	2014-06-27 11:38
MOT test number	105388374195
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
20 December 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	20 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-06-29
Last registration	2023-12-21
Complete history	<a href="#">See info</a>



Registration #1	2011-06-29	29 mi
Registration #2	2014-06-27	42.329 mi
Registration #3	2014-07-17	42.751 mi
Registration #4	2015-06-23	57.676 mi
Registration #5	2016-07-22	71.509 mi
Registration #6	2016-07-22	71.509 mi
Registration #7	2017-07-31	80.443 mi
Registration #8	2018-01-05	87.545 mi
Registration #9	2018-08-02	91.420 mi
Registration #10	2019-06-29	95.377 mi
Registration #11	2019-06-29	95.377 mi
Registration #12	2019-06-29	95.377 mi
Registration #13	2019-06-29	95.377 mi
Registration #14	2019-06-29	95.377 mi
Registration #15	2019-06-29	95.377 mi
Registration #16	2019-06-29	95.377 mi
Registration #17	2019-06-29	95.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1310 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	73137786