





report date: 2024-03-28

#### General information

Make	AUDI
Model	RS4 RS4 QUATTRO
Colour	Grey
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	4.9 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	415 BHP	
Max. torque	430 Nm at 5.500 rpm	
Engine capacity	4.163 cc	
Cylinders	8	
Fuel type	Petrol	
Consumption city	13.2 mpg	
Consumption extra urban	29.4 mpg	
Consumption combined	20.3 mpg	
CO2 emission	334 g/km	
CO2 label	M	



CarCheck.co.uk page 1/13



## Internet history

#### Entry 2

Date 2023-01-07

Pictures 47

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date 2022-07-01

Pictures 41

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-10-30
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	23
Total items failed	5

MOT #19	2023-10-31 11:09	
MOT test number	492140935926	
Result	✓ Passed	
Next expiry date	2024-10-30	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #18

MOT test number

Result

Rear Brake disc worn, pitted or scored, but not seriously weakened mainly on inside surfaces (1.1.14 (a) (ii))

MOT #17

MOT test number

464964440025

Result

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened mainly on inside surfaces (1.1.14 (a) (ii))

Pass with rectification detached (5.3.3 (a) (ii))

Offside Front Anti-roll bar attachment bracket/mounting likely to become

MOT #16	2022-08-30 15:52
MOT test number	681476770925
Result	✓ Passed

CarCheck.co.uk page 3/13



**MOT #15** 2021-07-31 09:11

**MOT test number** 292040088234

**Result** 
✓ Passed

**MOT #14** 2020-07-30 11:28

**MOT test number** 993145770069

**Result** ✓ Passed

**MOT #13** 2019-04-12 13:57

**MOT test number** 522548455754

Result 

Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #12** 2019-04-09 07:53

MOT test number 295893816030

**Result** X Failed

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Fail Electronic stability control warning lamp indicates a fault (7.12 (e))

Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11 2018-04-11 11:49

**MOT test number** 882568299243

**Result** ✓ Passed

CarCheck.co.uk page 4/13



MOT test number

Result

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

MOT #9	2017-03-20 13:52
MOT test number	258626944211
Result	<b>X</b> Failed
Fail Nearside Registration plate lamp not working (1.1.C.1d)	
Advice Offside Front Shock absorber has a light misting of oil (2.7.3)	
Advice Items removed from driver's view prior to test	
Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)	

MOT #8	2016-02-18 18:15
MOT test number	664708491166
Result	<b>✓</b> Passed
MOT #7	2015-02-06 16:17
MOT test number	405267935070
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/13



RJ07DHP

report date: 2024-03-28

MOT test number

445092644028

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5

MOT test number

Sesult

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

MOT test number

Result

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #3
 2012-01-12 12:28

 MOT test number
 868952812058

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



MOT #2

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1

MOT test number

582167370047

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



o micr mistory	
For how long did the current and previous owner(s) have this AUDI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	
*******	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	NK AIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-24
Last registration	2023-10-31
Complete history	See info



Registration #1	2007-03-24	17 mi
Registration #2	2010-03-18	34.543 mi
Registration #3	2011-03-14	35.772 mi
Registration #4	2012-01-12	36.292 mi
Registration #5	2013-01-21	52.971 mi
Registration #6	2013-01-21	52.971 mi
Registration #7	2014-02-11	63.880 mi
Registration #8	2015-02-06	72.154 mi
Registration #9	2016-02-18	77.345 mi
Registration #10	2017-03-20	82.067 mi
Registration #11	2017-03-20	82.067 mi
Registration #12		11.777 es
Registration #13		91.709 esi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		11.777 es
Registration #19		9.79 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 12/13



## Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1814 mm
Height	1391 mm
Length	4555 mm
Wheel base	2650 mm
Kerb weight	1845 kg
Max. allowed weight	2305 kg

# Additional information

Fuel tank capacity	63 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/1.