



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D5 SE LUX AWD
Colour	Gold
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	186 g/km
CO2 label	J






Internet history

Entry 1

Date	2022-01-12
Pictures	30
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2025-01-03
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	33
Total items failed	1

MOT #15	2023-12-08 14:41
MOT test number	614661598350
Result	✓ Passed
Next expiry date	2025-01-03

MOT #14	2022-12-22 12:42
MOT test number	170626549400
Result	✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-01-04 12:55
MOT test number	620855814056
Result	✓ Passed

MOT #12	2021-09-24 09:14
MOT test number	741076809914
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))

**MOT #11** 2020-10-01 09:41**MOT test number** 804295334431**Result** ✓ Passed**MOT #10** 2019-09-26 10:25**MOT test number** 897794542207**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn inside edge 2355517 (5.2.3 (e))**Minor** Central Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))**Advice** Covers & trays fitted**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-09-13 11:48**MOT test number** 397422507515**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge 235/55/17 (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge 235/55/17 (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge 235/55/17 (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view small chip in lower part of screen (3.2 (a) (i))

**MOT #8**

2018-09-13 09:24

MOT test number

391099918375

Result

✗ Failed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge 235/55/17 (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge 235/55/17 (5.2.3 (e))

Minor

Windscreen damaged but not adversely affecting driver's view small chip in lower part of screen (3.2 (a) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge 235/55/17 (5.2.3 (e))

MAJOR

Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

MOT #7

2017-09-14 13:00

MOT test number

358328387704

Result

✓ Passed

Advice

Offside Front Tyre worn close to the legal limit Inner edge worn 235/55/17 (4.1.E.1)

Advice

Nearside Front Tyre worn close to the legal limit Inner edge worn 235/55/17 (4.1.E.1)

MOT #6

2016-10-06 10:44

MOT test number

972078840735

Result

✓ Passed

Advice

Engine covers fitted

MOT #5

2015-09-22 11:33

MOT test number

369263504527

Result

✓ Passed

Advice

Advise engine covers and under trays fitted

**MOT #4** 2014-10-06 11:55**MOT test number** 249719174273**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** O/s/f tyres wearing on inner edge**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2014-10-06 11:55**MOT test number** 757049774255**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** O/s/f tyres wearing on inner edge**MOT #2** 2013-10-10 10:18**MOT test number** 385883583270**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-01-12 12:06**MOT test number** 309832413085**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Unable to obtain emissions reading



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
3 January 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	3 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-20
Current registration	*****
Plate since	2019-06-20

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-01-20
Last registration	2023-12-08
Complete history	See info



Registration #1	2010-01-20	21 mi
Registration #2	2013-01-12	37.208 mi
Registration #3	2013-10-10	45.947 mi
Registration #4	2014-10-06	56.411 mi
Registration #5	2015-09-22	66.495 mi
Registration #6	2016-10-06	77.990 mi
Registration #7	2017-09-14	87.493 mi
Registration #8	2018-09-13	98.236 mi
Registration #9	2019-09-13	108.979 mi
Registration #10	2020-09-13	119.722 mi
Registration #11	2021-09-13	130.465 mi
Registration #12	2022-09-13	141.208 mi
Registration #13	2023-09-13	151.951 mi
Registration #14	2024-09-13	162.694 mi
Registration #15	2025-09-13	173.437 mi
Registration #16	2026-09-13	184.180 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1879 kg
Max. allowed weight	2390 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	795781