



TK07GFT

report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO ACTIVE SPORT
Colour	Blue
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg



Internet history

Entry 1

Date	2021-05-29
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history****MOT #17** 2020-11-27 16:24**MOT test number** 229448544426**Result** ✓ Passed**Next expiry date** 2021-11-27

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Play in steering rack inner joint(s)

Advice Coil spring corroded rear both sides (5.3.1 (b) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16 2020-11-26 12:49**MOT test number** 451261769816**Result** ✗ Failed

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Coil spring corroded rear both sides (5.3.1 (b) (i))

Fail Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Play in steering rack inner joint(s)

**MOT #15** 2019-11-09 14:58**MOT test number** 587924135075**Result** ✓ Passed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Front sub frame corroded
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #14 2018-11-24 10:33**MOT test number** 398819264761**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13 2017-11-28 17:48**MOT test number** 489736557420**Result** ✓ Passed

- Advice** Offside Front Inner tyre wall slight damage
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #12** 2017-11-28 10:28**MOT test number** 140837230260**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front Inner tyre wall slight damage**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #11** 2016-11-27 14:42**MOT test number** 118059375634**Result** ✓ Passed**MOT #10** 2016-02-10 09:42**MOT test number** 450151116679**Result** ✓ Passed**MOT #9** 2015-02-13 13:23**MOT test number** 138344345449**Result** ✓ Passed**MOT #8** 2015-02-13 10:26**MOT test number** 125754545422**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

**MOT #7** 2014-02-26 15:08**MOT test number** 175087854465**Result** ✓ Passed**MOT #6** 2014-02-26 09:46**MOT test number** 778617454078**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #5** 2013-03-30 10:21**MOT test number** 898999583044**Result** ✓ Passed**Notice** Rear tyres cracking**Notice** O/s top mount dry**Notice** Rear coil springs corroded**MOT #4** 2012-03-19 11:46**MOT test number** 557439472017**Result** ✓ Passed**MOT #3** 2011-08-17 13:22**MOT test number** 379069721237**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2010-08-18 15:45
MOT test number	212450830298
Result	✓ Passed

MOT #1	2010-08-16 11:05
MOT test number	303068620244
Result	✗ Failed

Fail

Offside Rear Shock absorber has a serious fluid leak (2.7.3)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-07-31
Last registration	2020-11-27
Complete history	See info



Registration #1	2007-07-31	7 mi
Registration #2	2010-08-16	19.592 mi
Registration #3	2010-08-18	19.596 mi
Registration #4	2011-08-17	30.321 mi
Registration #5	2012-03-19	35.477 mi
Registration #6	2013-03-30	41.478 mi
Registration #7	2014-02-26	48.915 mi
Registration #8	2014-02-26	48.915 mi
Registration #9	2015-02-13	58.460 mi
Registration #10	2015-02-13	58.460 mi
Registration #11	2016-02-26	68.915 mi
Registration #12	2017-02-26	78.915 mi
Registration #13	2018-02-26	88.915 mi
Registration #14	2019-02-26	98.915 mi
Registration #15	2020-02-26	108.915 mi
Registration #16	2021-02-26	118.915 mi
Registration #17	2022-02-26	128.915 mi
Registration #18	2023-02-26	138.915 mi
Registration #19	2024-02-26	148.915 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	4087547