



report date: 2024-03-28

General information

Make	BMW
Model	316 116D
Colour	Blue
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	2.000 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	118 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-02-16
Pictures	17
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-15
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	52
Total items failed	4

MOT #19	2024-02-02 12:34
---------	------------------

MOT test number	454438119937
-----------------	--------------

Result	✓ Passed
Next expiry date	2025-02-15
Advice	Slight play both front drop links
Advice	Rear brake discs very worn corroded and lipped
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Tpms light on
Advice	Slight play offside front lower balljoint
Advice	Front brake discs very worn corroded and lipped
Advice	Parking brake just passed test,requires adjustment
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Nearside front side light not working

**MOT #18** 2023-02-15 09:44**MOT test number** 327169780856**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge on 3mm (205/55/16) (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 3mm, worn at the edges and light cracking (205/55/16) (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened slightly corroded and pads half worn on nearside (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on 3mm, worn at the edges and light cracking (205/55/16) (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (205/55/16) (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**Advice** Various suspension arm bushes slightly perished (front and rear)**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened slightly corroded and pads half worn (1.1.14 (a) (ii))**MOT #17** 2022-02-16 09:16**MOT test number** 370698600733**Result** ✓ Passed**MOT #16** 2021-04-07 08:28**MOT test number** 734268818171**Result** ✓ Passed

**MOT #15** 2021-04-06 09:30**MOT test number** 393629021669**Result** ✗ Failed

- MAJOR** Offside Headlamp aim too low (4.1.2 (a))
- MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))

**MOT #14** 2020-03-25 16:45**MOT test number** 732403472459**Result** ✓ Passed**MOT #13** 2020-03-25 11:39**MOT test number** 552095283290**Result** ✗ Failed

- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #12** 2019-04-10 16:16**MOT test number** 673076067002**Result** ✓ Passed

- Advice** Engine covers fitted
- Advice** Under trays fitted

**MOT #11** 2019-04-10 11:40**MOT test number** 848614007637**Result** ✗ Failed**MAJOR** Nearside Front Service brake excessively binding (1.2.1 (f))**Advice** Under trays fitted**MAJOR** Nearside Outer Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Engine covers fitted**MOT #10** 2018-03-19 10:34**MOT test number** 752041791107**Result** ✓ Passed**Advice** Child seat fitted**Advice** Under trays fitted**Advice** Engine covers fitted**MOT #9** 2018-03-19 10:34**MOT test number** 932535023035**Result** ✗ Failed**Advice** Engine covers fitted**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Child seat fitted**Advice** Under trays fitted

**MOT #8** 2017-04-07 08:28**MOT test number** 471802475941**Result** ✓ Passed**Advice** Under trays fitted**Advice** Engine covers fitted**MOT #7** 2016-04-05 08:36**MOT test number** 297840597290**Result** ✓ Passed**Advice** Under trays fitted**MOT #6** 2015-04-02 13:34**MOT test number** 137672895462**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2015-04-02 09:38**MOT test number** 106202495038**Result** ✗ Failed**Fail** Nearside rear parking (secondary) brakes imbalanced (3.7.B.6b)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Rear registration plate insecure (6.3.1b)**Notice** Under-trays fitted obscuring some underside components

**MOT #4** 2014-04-04 11:22**MOT test number** 629384094078**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2014-04-04 09:33**MOT test number** 847904894038**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Offside front tyre cracking**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** Nail in nearside front tyre**MOT #2** 2013-04-10 10:49**MOT test number** 668700903100**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2012-04-16 14:53**MOT test number** 787267202199**Result** ✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
15 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	15 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	<b>WG59DOH</b>
Plate since	2019-03-28
Current registration	<b>WG59DOH</b>
Plate since	2019-03-28

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-12-14
Last registration	2024-02-02
Complete history	<a href="#">See info</a>



Registration #1	2009-12-14	6 mi
Registration #2	2012-04-16	43.058 mi
Registration #3	2013-04-10	51.384 mi
Registration #4	2014-04-04	61.579 mi
Registration #5	2014-04-04	61.579 mi
Registration #6	2015-04-02	73.655 mi
Registration #7	2015-04-02	73.655 mi
Registration #8	2016-04-05	85.796 mi
Registration #9	2017-04-07	98.248 mi
Registration #10	2018-03-19	107.305 mi
Registration #11	2018-03-19	107.305 mi
Registration #12	2019-03-20	121.337 mi
Registration #13	2019-03-20	121.337 mi
Registration #14	2019-03-20	121.337 mi
Registration #15	2019-03-20	121.337 mi
Registration #16	2019-03-20	121.337 mi
Registration #17	2019-03-20	121.337 mi
Registration #18	2019-03-20	121.337 mi
Registration #19	2019-03-20	121.337 mi
Registration #20	2019-03-20	121.337 mi
Registration #21	2019-03-20	121.337 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1748 mm
Height	1421 mm
Length	4239 mm
Wheel base	2660 mm
Kerb weight	1305 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	94687259