



HONDA



Y767XGO


report date: 2024-03-28

General information

Make	HONDA
Model	S2000 16V
Colour	Black
Year of manufacture	2001
Top speed	150 mph
0 - 60 mph	6.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	236 BHP
Max. torque	204 Nm at 7.500 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.2 mpg
Consumption extra urban	35.8 mpg
Consumption combined	28.3 mpg
CO2 emission	237 g/km
CO2 label	L





## MOT history

MOT expiry date	2024-08-17
MOT pass rate	86 %
MOT passed	18
Failed MOT tests	3
Total advice items	21
Total items failed	8

MOT #21	2023-08-18 09:42
MOT test number	103930251446
Result	✓ Passed
Next expiry date	2024-08-17

MOT #20	2023-07-25 13:34
MOT test number	284709651947
Result	✗ Failed
Fail	Brake performance unable to be tested rear brakes excessively binding and brake pipe failed (1.2.1 (g))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Nearside Front Fuel pipe leaking excessively or a risk of fire under vehicle behind plastic cover (6.1.3 (b) (ii))
Fail	Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Fail	Offside Rear Brake pipe at imminent risk of failure or fracture corroded and leaking (1.1.11 (a))

MOT #19	2022-03-02 14:57
MOT test number	678169708527
Result	✓ Passed

MOT #18	2021-03-19 10:41
MOT test number	592919866003
Result	✓ Passed

**MOT #17**

2020-09-29 08:26

**MOT test number**

203117937557

**Result**

✓ Passed

- Advice** N/s/r sill end corroding
- Advice** Front tyres badly perished
- Advice** Rust and corrosion to underside

**MOT #16**

2019-08-05 12:30

**MOT test number**

570579464102

**Result**

✓ Passed

- Advice** Front inner under sills/floors corroding
- Advice** Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rust & corrosion in various places
- Advice** N/s/r outer sill/arch corroding

**MOT #15**

2019-08-02 08:08

**MOT test number**

951569274431

**Result**

✗ Failed

- Advice** N/s/r outer sill/arch corroding
- Fail** Offside Rear Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))
- Advice** Front inner under sills/floors corroding
- Fail** Electrical wiring insecure and connectors likely to become disconnected under passenger seat (4.11 (a) (ii))
- Advice** Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rust & corrosion in various places

**MOT #14** 2018-08-02 10:52**MOT test number** 470051769416**Result** ✓ Passed**Advice** Front wipers slight smear**MOT #13** 2018-07-24 14:04**MOT test number** 504424342873**Result** ✗ Failed**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Front wipers slight smear**MOT #12** 2017-08-07 15:32**MOT test number** 747154995139**Result** ✓ Passed**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #11** 2016-09-01 15:00**MOT test number** 957912661066**Result** ✓ Passed**MOT #10** 2015-09-10 12:43**MOT test number** 137055666168**Result** ✓ Passed



<b>MOT #9</b>	2014-09-02 12:30
<b>MOT test number</b>	189065244281
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #8</b>	2013-07-24 11:52
<b>MOT test number</b>	735955603263
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2012-08-14 08:48
<b>MOT test number</b>	515137822275
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Notice</b>	Oil leak

<b>MOT #6</b>	2011-08-23 10:43
<b>MOT test number</b>	668785331285
<b>Result</b>	✓ Passed

<b>MOT #5</b>	2010-10-02 09:03
<b>MOT test number</b>	763755270266
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2009-09-26 10:53
<b>MOT test number</b>	544289369284
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2008-09-26 17:01
<b>MOT test number</b>	773150778265
<b>Result</b>	✓ Passed



MOT #2	2007-09-22 11:10
MOT test number	302735567420
Result	✓ Passed
MOT #1	2006-10-03 11:48
MOT test number	822766776207
Result	✓ Passed



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	<b>Y767XGO</b>
Plate since	2024-03-28
Current registration	<b>Y767XGO</b>
Plate since	2024-03-28

More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2001-08-11
Last registration	2023-08-18
Complete history	<a href="#">See info</a>



Registration #1	2001-08-11	24 mi
Registration #2	2006-10-03	19.123 mi
Registration #3	2007-09-22	23.074 mi
Registration #4	2008-09-26	26.991 mi
Registration #5	2009-09-26	30.946 mi
Registration #6	2010-10-02	35.177 mi
Registration #7	2011-08-23	38.505 mi
Registration #8	2012-08-14	55.000 mi
Registration #9	2013-07-24	62.645 mi
Registration #10	2014-09-02	70.147 mi
Registration #11	2015-09-10	81.364 mi
Registration #12	2016-09-10	91.364 mi
Registration #13	2017-09-10	101.364 mi
Registration #14	2018-09-10	111.364 mi
Registration #15	2019-09-10	121.364 mi
Registration #16	2020-09-10	131.364 mi
Registration #17	2021-09-10	141.364 mi
Registration #18	2022-09-10	151.364 mi
Registration #19	2023-09-10	161.364 mi
Registration #20	2024-09-10	171.364 mi
Registration #21	2025-09-10	181.364 mi
Registration #22	2026-09-10	191.364 mi

More info >



Dimensions & weight

Width	1860 mm
Height	1285 mm
Length	4135 mm
Kerb weight	1250 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	F20C21010974