





General information

Make	AUDI
Model	A6 TDI S LINE
Colour	Blue
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	172 g/km
CO2 label	Н





MOT history

MOT expiry date	2025-01-22
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	19
Total items failed	8

MOT #19	2024-01-20 16:21
MOT test number	210111002318
Result	✓ Passed
Next expiry date	2025-01-22

MOT #18		2023-01-12 10:23
MOT test number		954728930250
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #17	2022-01-22 15:53
MOT test number	322874570000
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2021-01-22 18:05
MOT test number	368013319301
Result	✓ Passed





MOT #15	2019-07-10 15:30
MOT test number	423017299302
Result	✓ Passed
AdviceChild Seat fitted not allowing full inspection of adult beltMinorWindscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #14	1 2018-07-10) 14:49
MOT test	t number 7450697	746745
Result	✓	Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))		
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #13	2018-07-02 15:39
MOT test number	716699171371
Result	× Failed
Advice Nearside Front Shock absorbers light misting of oil or has limited damping e	effect (5.3.2 (b))
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Fail Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #12	2017-07-03 10:03
MOT test number	377334134874
Result	✓ Passed





MOT #11		2016-07-04 09:20
MOT test number		582880527294
Result		✓ Passed
MOT #10		2016-07-04 09:19
MOT test number		683699646755
Result		🗙 Failed
Pass with rectification	Nearside Rear Registration plate lamp not working (1.1.C.1d)	
МОТ #9		2015-07-22 11:04
MOT test number		677033405225
Result		✓ Passed
MOT #8		2014-07-01 10:45
MOT test number		325262484183
Result		✓ Passed

MOT #7	2014-06-30 09:27
MOT test number	547101784180
Result	🗙 Failed
FailNearside Front Upper Suspension arm has excessive play in a ball joint (2.4.G.2)AdviceOffside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #6		2013-06-25 09:48
MOT test	number	525906073106
Result		✓ Passed
Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)		
Notice	N/side rear tyre worn on inner edge	



MOT #5	2013-06-24 10:51
MOT test number	338315473148
Result	🗙 Failed
Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	
Fail Brakes imbalanced across an axle (3.7.B.5b)	
Notice N/side rear tyre worn on inner edge	
Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.2	3.1a)

МОТ #4	2012-07-06 09:57
MOT test number	146168582151
Result	✓ Passed

МОТ #3	2011-06-24 09:38
MOT test number	227785071434
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #2	2010-07-23 17:07
MOT test number	274204100279
Result	✓ Passed

MOT #1	2009-09-24 09:32
MOT test number	294747869297
Result	✓ Passed

KV56LSF

report date: 2024-03-28



Tax & MOT check

✓ Taxed Tax due: 1 March 2025	Expires: 22 January 2025	✓ MOT
Tax status		Valid until 1 March
Days left MOT expiry date		307 22 January 2025
Full MOT history		<u>See MOT history</u>

Tax calculation

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-10-12
Last registration	2024-01-20
Complete history	See info



2006-10-12	13 mi
2009-09-24	34.503 mi
2010-07-23	38.834 mi
2011-06-24	49.166 mi
2012-07-06	57.692 mi
2013-06-24	73.899 mi
2013-06-25	73.899 mi
2014-06-30	89.939 mi
2014-07-01	89.939 mi
2015-07-22	105.718 mi
2015-07-22	105./18/00
2013-07-22	105.718 111
	105.718 m
	105.718 m
	2009-09-24 2010-07-23 2011-06-24 2012-07-06 2013-06-24 2013-06-25 2014-06-30 2014-07-01





Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1855 mm
Height	1459 mm
Length	4916 mm
Wheel base	2843 mm
Kerb weight	1540 kg
Max. allowed weight	2120 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	BRE 025730