



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI BLACK EDITION
Colour	Black
Year of manufacture	2016
Top speed	107 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	123 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-08-13
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-18
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #7	2023-10-19 11:11
MOT test number	354691039646
Result	✓ Passed
Next expiry date	2024-10-18

MOT #6	2022-09-08 09:08
MOT test number	796290655290
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2021-07-20 11:02
MOT test number	363887425934
Result	✓ Passed

MOT #4	2020-11-26 16:42
MOT test number	901258733925
Result	✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front position lamp in poor condition

**MOT #3** 2020-11-26 13:13**MOT test number** 411308287686**Result** ✗ Failed**Advice** Nearside Front position lamp in poor condition**Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #2** 2019-12-12 14:34**MOT test number** 935734671696**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2019-12-12 14:34**MOT test number** 677744819191**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
18 October 2024

Tax status		Valid until 1 November
Days left		187
MOT expiry date		18 October 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GL66RPZ
Plate since	2019-06-29
Current registration	 GL66RPZ
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-12-23
Last registration	2023-10-19
Complete history	See info



Registration #1	2016-12-23	25 mi
Registration #2	2019-12-12	66.597 mi
Registration #3	2019-12-12	66.597 mi
Registration #4	2020-11-26	79.235 mi
Registration #5	2020-11-26	79.235 mi
Registration #6	2020-11-26	79.235 mi
Registration #7	2020-11-26	79.235 mi
Registration #8	2020-11-26	79.235 mi
Registration #9	2020-11-26	79.235 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	2062 mm
Height	1823 mm
Length	4408 mm
Wheel base	2681 mm
Kerb weight	1594 kg
Max. allowed weight	2141 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	2

Number of axles	2
Engine number	DFSD096482