



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Grey
Year of manufacture	2011
Top speed	131 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-07-28
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-14
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	16
Total items failed	1

MOT #12	2023-07-10 08:40
MOT test number	296538527360
Result	✓ Passed
Next expiry date	2024-07-14

MOT #11	2022-07-08 15:07
MOT test number	849816038524
Result	✓ Passed
Advice	Suspension arm pin or bush worn but not resulting in excessive movement all rear arm bushes perished (5.3.4 (a) (i))
Advice	Nearside Front Nail in tyre
Advice	Offside Rear Tyre slightly damaged/cracking or perishing perished to outer wall (5.2.3 (d) (ii))
Advice	Exhaust centre section corroded clamp
Advice	Rear Tyre slightly damaged/cracking or perishing both wearing uneven to inner edge of tread (5.2.3 (d) (ii))

MOT #10	2021-07-15 07:59
MOT test number	298895001895
Result	✓ Passed

**MOT #9** 2021-07-14 15:42**MOT test number** 910282760609**Result** ✗ Failed**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #8** 2020-10-14 07:48**MOT test number** 131647038193**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing due to non driven distortion, not structural failure. So benefit of doubt given. (5.2.3 (d) (ii))**Minor** Nearside Rear Direction indicator with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing due to non driven distortion, not structural failure. So benefit of doubt given. (5.2.3 (d) (ii))**MOT #7** 2019-10-22 08:07**MOT test number** 536775795592**Result** ✓ Passed**MOT #6** 2018-10-09 08:06**MOT test number** 197686265978**Result** ✓ Passed**MOT #5** 2017-10-11 08:06**MOT test number** 899435361079**Result** ✓ Passed

**MOT #4** 2016-10-05 15:43**MOT test number** 760828825477**Result** ✓ Passed**Advice** Rear tyre worn low**Advice** Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #3** 2016-10-05 15:43**MOT test number** 816322780933**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator obscured more than 50% (1.4.A.2d)**Advice** Rear tyre worn low**Advice** Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**MOT #2** 2015-10-07 17:07**MOT test number** 146887614872**Result** ✓ Passed**Advice** Rear tyres starting to craze and wearing inner edges.**MOT #1** 2014-10-22 09:11**MOT test number** 685045994219**Result** ✓ Passed**Notice** All brake discs pitted/corroded



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
14 July 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	14 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 DV61KWA
Plate since	2019-06-29
Current registration	 DV61KWA
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-10-31
Last registration	2023-07-10
Complete history	See info



Registration #1	2011-10-31	22 mi
Registration #2	2014-10-22	22.458 mi
Registration #3	2015-10-07	29.472 mi
Registration #4	2016-10-05	36.627 mi
Registration #5	2016-10-05	36.627 mi
Registration #6	2017-10-11	42.999 mi
Registration #7	2018-10-09	51.361 mi
Registration #8	2019-10-09	55.377 mi
Registration #9	2019-10-09	55.377 mi
Registration #10	2019-10-09	55.377 mi
Registration #11	2019-10-09	55.377 mi
Registration #12	2019-10-09	55.377 mi
Registration #13	2019-10-09	55.377 mi
Registration #14	2019-10-09	55.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1523 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles

2

Engine number

CBA 754507