





report date: 2024-03-29

### General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Grey
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



## MOT history

MOT expiry date	2025-03-17
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	10
Total items failed	6

MOT #16	2024-02-29 08:45
MOT test number	299514118907
Result	✓ Passed
Next expiry date	2025-03-17
Minor (b) (i))  Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1	

MOT #15		2023-03-16 15:04
MOT test	number	117116791062
Result		✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #14	2022-03-18 17:36
MOT test number	917140279314
Result	✓ Passed
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or	r cords (5.2.3 (d) (i))

CarCheck.co.uk page 3/13



**MOT #13** 2022-03-16 10:18

MOT test number 242497674917

Result

× Failed

Advice

Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #12** 2021-03-16 16:08

MOT test number 211726247051

**Result** ✓ Passed

Advice

Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**MOT #11** 2021-03-16 13:55

MOT test number 622758056832

Result X Failed

Fail

Offside Headlamp aim too low (4.1.2 (a))

Advice

Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

Fail

Nearside Headlamp aim too low (4.1.2 (a))

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #10** 2020-09-03 12:00

MOT test number 646291322306

**Result** 
✓ Passed

**Advice** 

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/13



MOT #9	2020-09-03 10:21
MOT test number	738634404696
Result	<b>×</b> Failed
Fail Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))  Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (	5.2.3 (e))
MOT #8	2019-09-26 11:49
MOT test number	793664398058
Result	<b>✓</b> Passed
MOT #7	2018-10-10 09:35
MOT test number	768019258477
Result	<b>✓</b> Passed
MOT #6	2017-10-31 16:15
MOT test number	146646887624
Result	✓ Passed
MOT #5	2017-02-28 15:42
MOT test number	845156257603
Result	<b>✓</b> Passed
MOT #4	2016-02-29 13:37
MOT test number	972892469644
Result	<b>✓</b> Passed
MOT #3	2015-03-09 13:27
MOT test number	175028365412
Result	✓ Passed

CarCheck.co.uk page 5/13



 MOT #2
 2014-03-17 16:00

 MOT test number
 398746874088

 Result
 ✓ Passed

 MOT #1
 2014-03-17 16:00

 MOT test number
 708996774049

 Result
 X Failed

 Pass with rectification
 Nearside Headlamp aim too high (1.8)

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	17 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 9/13



$\sim$		
Owner	hictory	7
OWITCE	1113601	7

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
************	
***************************************	
*********	
***************************************	
**************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	IIK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



## Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-05-31
Last registration	2024-02-29
Complete history	See info



Registration #1	2011-05-31	17 mi
Registration #2	2014-03-17	20.784 mi
Registration #3	2015-03-09	22.827 mi
Registration #4	2016-02-29	24.643 mi
Registration #5	2017-02-28	26.449 mi
Registration #6	2017-10-31	27.803 mi
Registration #7	2018-10-10	36.067 mi
Registration #8	2019-09-26	44.679 mi
Registration #9	2020-09-03	51.586 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		n.m.

More info >

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



# Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

# Additional information

Fuel tank capacity	52 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles2Engine number1760212