






report date: 2024-03-29

#### General information

Make	JAGUAR
Model	XKR XJ8
Colour	Blue
Year of manufacture	1998
Top speed	150 mph
0 - 60 mph	6.9 seconds
Gearbox	5 speed automatic

### Engine & fuel consumption

Power	290 BHP
Max. torque	393 Nm at 4.250 rpm
Engine capacity	3.996 сс
Cylinders	8
Fuel type	Petrol
Consumption city	16.3 mpg
Consumption extra urban	32.2 mpg
Consumption combined	23.8 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-29

### Internet history

#### Entry 1

Date 2021-07-01

Pictures 81

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



report date: 2024-03-29

2022-09-16 12:24

NAC	\Т	بہا: حا	L
MC	ノレ	nis	tory

MOT #18

MOT expiry date	2024-10-31
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	11
Total items failed	14

MOT #19		2023-11-01 10:39
MOT test	number	740144987756
Result		✓ Passed
Next exp	iry date	2024-10-31
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))		
Minor  Nearside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice	Surface corrosion	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT test number	303320309092
Result	✓ Passed
MOT #17	2021-06-09 14:42
MOT test number	105471722391
Result	✓ Passed
Advice Rear Brake discs slightly pitted	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #16** 2018-10-18 16:04

MOT test number 272630620453

**Result** ✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2018-10-11 14:16

**MOT test number** 530480538840

**Result** X Failed

**Fail** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner arch, behind subframe (5.3.6 (a) (i))

**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

Fail Brake pedal has insufficient reserve travel (1.1.2 (a))

Fail Offside Front Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))

Fail Offside Front Lower Shock absorbers has an excessively worn bush (5.3.2 (c))

**Fail** Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner arch, behind subframe (5.3.6 (a) (i))

**Fail** Nearside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Fail Offside Front Direction indicator incorrect colour (4.4.3 (a))

Fail Brake performance not tested (1.2.1 (g))

**Advice** Offside front floor corroded, outside prescribed area.

Fail Brake fluid significantly below minimum mark (1.1.10 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Lower Shock absorbers has an excessively worn bush (5.3.2 (c))

**MOT #14** 2017-12-22 15:57

MOT test number 279205178359

**Result** ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #13 2017-12-14 10:15

**MOT test number** 465266017362

Result × Failed

**Fail** Nearside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**Fail** Nearside rear brake binding (3.7.B.1)

MOT #12 2016-12-07 12:04

**MOT test number** 785288171476

**Result** 
✓ Passed

**MOT #11** 2015-12-21 12:25

**MOT test number** 878464785489

MOT #10 2014-12-18 15:16

**MOT test number** 485962054397

**Result** ✓ Passed

MOT #9 2014-01-04 08:25

**MOT test number** 595124904098

**Result** ✓ Passed

MOT #8 2012-08-03 11:12

**MOT test number** 169136712217

**Result** ✓ Passed

MOT #7 2011-04-04 11:33

**MOT test number** 366474591001

CarCheck.co.uk page 5/13



MOT #3

Result

**MOT** test number

**S457RVW** 

report date: 2024-03-29

2008-06-25 11:40

702037178168

✓ Passed

MOT #6	2011-04-04 11:33
MOT test number	745494691021
Result	<b>★</b> Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (8.2.3)
MOT #5	2010-03-12 12:03
MOT test number	712381670003
Result	✓ Passed
MOT #4	2009-03-31 09:53
MOT test number	210610299044
Result	✓ Passed

MOT #2	2007-08-01 17:22
MOT test number	693383517238
Result	✓ Passed

MOT #1	2006-07-31 10:05
MOT test number	322192016224
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

#### Tax & MOT check



Tax status

Days left

MOT expiry date

Full MOT history

See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	history
OWITCH	THISCOLY

For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
**********	
***************************************	
***********	
********	
***************************************	
	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	SIF.
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	1998-08-20
Last registration	2023-11-01
Complete history	See info



Registration #1	1998-08-20	22 mi
Registration #2	2006-07-31	54.107 mi
Registration #3	2007-08-01	56.526 mi
Registration #4	2008-06-25	58.958 mi
Registration #5	2009-03-31	62.271 mi
Registration #6	2010-03-12	64.016 mi
Registration #7	2011-04-04	65.349 mi
Registration #8	2012-08-03	66.080 mi
Registration #9	2014-01-04	68.376 mi
Registration #10	2014-12-18	69.002 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.117 es

More info >

CarCheck.co.uk page 12/13



S457RVW report date: 2024-03-29

Dimensions & weight

Width	1799 mm
Height	1333 mm
Length	5149 mm

## Additional information

Fuel tank capacity	81 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	BC9806211311

CarCheck.co.uk page 13/13