



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | POLO SEL TDI |
| Colour | Silver |
| Year of manufacture | 2011 |
| Top speed | 106 mph |
| 0 - 60 mph | 11.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 90 BHP |
| Max. torque | 195 Nm at 1.500 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 55.4 mpg |
| Consumption extra urban | 78.5 mpg |
| Consumption combined | 67.3 mpg |
| CO2 emission | 112 g/km |
| CO2 label | C |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-14 |
| Pictures | 7 |
| Listing price | View report |



source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-21 |
| MOT pass rate | 59 % |
| MOT passed | 10 |
| Failed MOT tests | 7 |
| Total advice items | 28 |
| Total items failed | 7 |

| | |
|------------------|---|
| MOT #17 | 2023-07-22 07:26 |
| MOT test number | 475173018932 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-21 |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |

| | |
|-------------------------|--|
| MOT #16 | 2023-07-17 14:22 |
| MOT test number | 431294733215 |
| Result | ✗ Failed |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |
| MAJOR | Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) |
| Pass with rectification | Nearside Front Headlamp aim too low (4.1.2 (a)) |
| Advice | Nearside Rear Brake pipe clips or supports missing, pipe adequately supported (1.1.11 (d) (i)) |

| | |
|-----------------|------------------|
| MOT #15 | 2022-12-08 11:33 |
| MOT test number | 480622490027 |
| Result | ✓ Passed |



| | |
|-------------------------|---|
| MOT #14 | 2022-12-08 11:33 |
| MOT test number | 585062065519 |
| Result | ✗ Failed |
| Pass with rectification | Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) |

| | |
|-----------------|--|
| MOT #13 | 2022-01-10 15:12 |
| MOT test number | 649454778947 |
| Result | ✓ Passed |
| Advice | Offside Front Shock absorbers has light misting of oil (5.3.2 (b)) |

| | |
|-----------------|---|
| MOT #12 | 2021-12-22 10:09 |
| MOT test number | 958345705594 |
| Result | ✗ Failed |
| MAJOR | Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) |
| MAJOR | Nearside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i)) |
| MAJOR | Exhaust has a major leak of exhaust gases (6.1.2 (a)) |
| MAJOR | Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |
| MAJOR | Front Brakes imbalanced across an axle (1.2.1 (b) (i)) |
| MAJOR | Offside Front Position lamp not working (4.2.1 (a) (ii)) |
| MAJOR | Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) |
| MAJOR | Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i)) |
| Advice | Offside Front Shock absorbers has light misting of oil (5.3.2 (b)) |
| MAJOR | Offside Headlamp insecure (4.1.1 (c)) |
| MAJOR | Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c)) |

**MOT #11** 2020-12-23 14:29**MOT test number** 298054161273**Result** ✓ Passed**MOT #10** 2020-12-22 12:50**MOT test number** 521105688947**Result** ✗ Failed**DANGEROUS** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))**DANGEROUS** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MAJOR** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))**MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MOT #9** 2019-08-23 10:16**MOT test number** 184961469491**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))**MOT #8** 2018-08-17 13:44**MOT test number** 584647477606**Result** ✓ Passed**MOT #7** 2017-09-01 13:10**MOT test number** 447016652452**Result** ✓ Passed

**MOT #6** 2017-09-01 10:43**MOT test number** 344288223259**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #5** 2016-09-08 12:16**MOT test number** 854691313611**Result** ✓ Passed**Advice** Tyres starting to perish**MOT #4** 2016-09-06 09:59**MOT test number** 562434695130**Result** ✗ Failed**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)**Advice** Rear brake discs corroded**Advice** Tyres starting to perish**Advice** Exhaust sleeve corroded**Fail** Offside Front wheel bearing rough when rotated (2.5.A.2)**Advice** Front brake discs corroded**MOT #3** 2015-08-17 08:03**MOT test number** 684090915659**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #2 | 2014-08-18 14:51 |
| MOT test number | 395910034426 |
| Result | ✓ Passed |

| | |
|-------------------------|---|
| MOT #1 | 2014-08-18 14:51 |
| MOT test number | 279180034231 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Front Wheel bolt(s) missing (4.2.A.1e) |



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
21 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 278 |
| MOT expiry date | 21 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  SV61MXO |
| Plate since | 2024-03-28 |
| Current registration |  SV61MXO |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2011-09-08 |
| Last registration | 2023-07-22 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-09-08 | 20 mi |
| Registration #2 | 2014-08-18 | 36.518 mi |
| Registration #3 | 2015-08-17 | 47.963 mi |
| Registration #4 | 2016-09-06 | 56.173 mi |
| Registration #5 | 2016-09-08 | 56.173 mi |
| Registration #6 | 2017-09-01 | 60.138 mi |
| Registration #7 | 2017-09-01 | 60.138 mi |
| Registration #8 | 2018-08-17 | 65.382 mi |
| Registration #9 | 2019-08-23 | 68.865 mi |
| Registration #10 | 2020-08-23 | 72.348 mi |
| Registration #11 | 2021-08-23 | 75.831 mi |
| Registration #12 | 2022-08-23 | 79.314 mi |
| Registration #13 | 2023-07-22 | 82.797 mi |
| Registration #14 | 2023-07-22 | 82.797 mi |
| Registration #15 | 2023-07-22 | 82.797 mi |
| Registration #16 | 2023-07-22 | 82.797 mi |
| Registration #17 | 2023-07-22 | 82.797 mi |
| Registration #18 | 2023-07-22 | 82.797 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 90% |
| Children | 86% |
| Pedestrian | 41% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|-------------|---------|
| Width | 1682 mm |
| Height | 1485 mm |
| Length | 3970 mm |
| Wheel base | 2470 mm |
| Kerb weight | 1157 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|---|
| Number of axles | 2 |
|-----------------|---|

| | |
|---------------|------------|
| Engine number | CAY 593392 |
|---------------|------------|