



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 S COUPE CABRIOLET
Colour	Blue
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	10.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-09
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history**

MOT #20	2021-12-09 09:42
MOT test number	670719472669
Result	✓ Passed
Next expiry date	2022-12-08

MOT #19	2021-12-07 15:01
MOT test number	796508312089
Result	✗ Failed

Fail Emissions not tested Catalyst over heating due to missfire (8.2.1.2 (d))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #18	2021-01-14 14:57
MOT test number	859191620683
Result	✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm,outer wall damaged (5.2.3 (e))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Play in steering rack inner joint(s)

Advice Oil leak, but not excessive gearbox (8.4.1 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm,devoid of tread on inner edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge inner and outer edges low (5.2.3 (e))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #17**

2021-01-14 14:57

MOT test number

243797640259

Result**✗ Failed**

- Advice** Play in steering rack inner joint(s)
- Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm, outer wall damaged (5.2.3 (e))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm, devoid of tread on inner edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner and outer edges low (5.2.3 (e))

MOT #16

2019-07-16 12:58

MOT test number

538586056772

Result**✓ Passed**

- Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing outer wall damaged (5.2.3 (d) (ii))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Supplementary restraint system warning lamp does not illuminate air bag light (7.1.6 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #15**

2019-07-12 15:30

MOT test number

314729066107

Result**✗ Failed**

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing outer wall damaged (5.2.3 (d) (ii))
- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Supplementary restraint system warning lamp does not illuminate air bag light (7.1.6 (a))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14

2018-07-24 16:33

MOT test number

621332156508

Result**✓ Passed**

- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing outer wall (5.2.3 (d) (i))

**MOT #13**

2018-07-24 08:01

MOT test number

562686493245

Result

✗ Failed

Fail

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing outer wall (5.2.3 (d) (i))

Advice

Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail

Offside Rear Position lamp not working (4.2.1 (a))

Advice

Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12

2017-07-20 15:34

MOT test number

339391546115

Result

✓ Passed

Advice

Offside Front Direction indicators slightly discoloured (1.4.A.2f)

Advice

Nearside Front Direction indicators slightly discoloured (1.4.A.2f)

MOT #11

2016-07-01 09:53

MOT test number

555390878109

Result

✓ Passed

Advice

Offside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice

Items removed from driver's view prior to test

Advice

Engine covers fitted

Advice

Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2015-07-07 16:33**MOT test number** 289938085433**Result** ✓ Passed**MOT #9** 2015-07-07 09:58**MOT test number** 496958685176**Result** ✗ Failed**Notice** Rear brake discs worn/corroded**Fail** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Notice** Wipers split**Notice** Front brake discs lipped/worn**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2014-07-21 15:07**MOT test number** 537832904270**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2013-07-04 13:06**MOT test number** 286125783451**Result** ✓ Passed**MOT #6** 2012-07-26 16:42**MOT test number** 506698802242**Result** ✓ Passed

**MOT #5** 2012-04-05 14:11**MOT test number** 417556992022**Result** ✓ Passed**MOT #4** 2011-04-05 16:39**MOT test number** 388865791038**Result** ✓ Passed**MOT #3** 2010-06-23 14:49**MOT test number** 273324770410**Result** ✓ Passed**MOT #2** 2010-06-23 09:36**MOT test number** 401144370169**Result** ✗ Failed

- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front Headlamp aim too low (1.8)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front Headlamp aim too low (1.8)

MOT #1 2009-06-25 10:03**MOT test number** 324836279132**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-06-30
Last registration	2021-12-09
Complete history	See info



Registration #1	2006-06-30	18 mi
Registration #2	2009-06-25	13.919 mi
Registration #3	2010-06-23	18.593 mi
Registration #4	2010-06-23	18.593 mi
Registration #5	2011-04-05	20.962 mi
Registration #6	2012-04-05	28.341 mi
Registration #7	2012-07-26	30.573 mi
Registration #8	2013-07-04	35.245 mi
Registration #9	2014-07-21	49.493 mi
Registration #10	2015-07-07	58.816 mi
Registration #11	2015-07-07	58.816 mi
Registration #12	2016-07-07	58.816 mi
Registration #13	2017-07-07	58.816 mi
Registration #14	2018-07-07	58.816 mi
Registration #15	2019-07-07	58.816 mi
Registration #16	2020-07-07	58.816 mi
Registration #17	2021-07-07	58.816 mi
Registration #18	2022-07-07	58.816 mi
Registration #19	2023-07-07	58.816 mi
Registration #20	2024-07-07	58.816 mi
Registration #21	2025-07-07	58.816 mi
Registration #22	2026-07-07	58.816 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1543 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	LH4P1445371