



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 RHYTHM
Colour	Black
Year of manufacture	-
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-13
Pictures	27
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #16	2021-08-18 15:16
MOT test number	238799384562
Result	✓ Passed
Next expiry date	2022-09-02
Advice	O/s/f wheel bearing slightly noisy

MOT #15	2020-09-03 12:41
MOT test number	289635126022
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside front tyre on 2 mm and perishing
Advice	Offside rear tyre heavily perishing

MOT #14	2020-09-03 12:41
MOT test number	273153460391
Result	✗ Failed
Advice	Offside front tyre on 2 mm and perishing
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside rear tyre heavily perishing
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #13	2019-08-23 13:36
MOT test number	663590550627
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both front tyre edges worn (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12** 2019-08-20 15:22**MOT test number** 608642368133**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both front tyre edges worn (5.2.3 (e))**MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #11** 2018-08-09 12:34**MOT test number** 915871820351**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #10** 2017-07-28 14:58**MOT test number** 338909897402**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)

**MOT #9** 2017-07-28 14:03**MOT test number** 147845121971**Result** ✗ Failed**Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Fail** Offside Rear Direction indicator incorrect colour DISCOLOURED (1.4.A.2f)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2016-07-30 08:56**MOT test number** 206272550755**Result** ✓ Passed**MOT #7** 2016-07-21 14:07**MOT test number** 478558252453**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Offside Rear Rear fog lamp not working (1.3.2b)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Direction indicators not working (1.4.A.2c)**Advice** Oil leak from engine /sump/oil filter housing**Fail** Passenger's seat insecure (6.2.A.1)

**MOT #6** 2015-06-29 17:30**MOT test number** 676760885124**Result** ✓ Passed**Notice** Oil leak**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2015-06-29 15:15**MOT test number** 366770985159**Result** ✗ Failed**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Oil leak**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2014-04-30 13:55**MOT test number** 119010424136**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2014-04-30 11:33**MOT test number** 196200824194**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #2	2013-02-04 16:27
MOT test number	985315033045
Result	✓ Passed
MOT #1	2012-02-04 11:21
MOT test number	549615832058
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-01-24
Last registration	2021-08-18
Complete history	See info



Registration #1	2009-01-24	24 mi
Registration #2	2012-02-04	16.049 mi
Registration #3	2013-02-04	21.505 mi
Registration #4	2014-04-30	27.729 mi
Registration #5	2014-04-30	27.729 mi
Registration #6	2015-06-29	32.939 mi
Registration #7	2015-06-29	32.939 mi
Registration #8	2016-07-21	36.203 mi
Registration #9	2016-07-30	36.227 mi
Registration #10	2016-07-30	36.227 mi
Registration #11	2016-07-30	36.227 mi
Registration #12	2016-07-30	36.227 mi
Registration #13	2016-07-30	36.227 mi
Registration #14	2016-07-30	36.227 mi
Registration #15	2016-07-30	36.227 mi
Registration #16	2016-07-30	36.227 mi
Registration #17	2016-07-30	36.227 mi
Registration #18	2016-07-30	36.227 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1477 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	932 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7W5014606