




report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA EXCLUSIVE 16V PICASSO E4
Colour	Grey
Year of manufacture	2006
Top speed	119 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	191 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	32.8 mpg
CO2 emission	205 g/km
CO2 label	K






Internet history

Entry 1

Date	2022-01-25
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-13
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	32
Total items failed	11

MOT #23	2024-01-16 10:17
MOT test number	972838001431
Result	✓ Passed
Next expiry date	2025-02-13
Minor	Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #22	2023-01-25 16:24
MOT test number	155136354524
Result	✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #21** 2023-01-19 18:20**MOT test number** 801499137859**Result** ✗ Failed

- Advice** Exhaust shield unsecure rear box
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Oil leaking excessively from engine (8.4.1 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))

MOT #20 2022-02-14 12:34**MOT test number** 825985163386**Result** ✓ Passed**MOT #19** 2021-05-18 10:06**MOT test number** 952363096368**Result** ✓ Passed

- Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Both outer sills damaged

**MOT #18**

2021-05-17 10:54

MOT test number

705663758757

Result

✗ Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Both outer sills damaged

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17

2020-05-20 10:16

MOT test number

618190084232

Result

✓ Passed

MOT #16

2019-07-10 09:02

MOT test number

508198871191

Result

✓ Passed

Advice Nearside damage to outer sill area but not considered excessive

Advice Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Offside Rear Suspension component mounting prescribed area damaged but not considered excessive outer sill area (5.3.6 (a) (i))

MOT #15

2018-07-12 14:02

MOT test number

325111202113

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))

Advice Offside Rear damage to outer sill end but not considered structural

**MOT #14** 2018-07-12 10:53**MOT test number** 582576943500**Result** ✗ Failed**Advice** Offside Rear damage to outer sill end but not considered structural**Advice** Offside Front Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))**Fail** Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))**MOT #13** 2017-06-15 09:34**MOT test number** 772375226326**Result** ✓ Passed**MOT #12** 2016-06-16 09:20**MOT test number** 769674793200**Result** ✓ Passed**MOT #11** 2015-07-06 13:24**MOT test number** 365737785175**Result** ✓ Passed**Notice** O/s/r tyre perished.**MOT #10** 2015-07-06 10:43**MOT test number** 285707185173**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** O/s/r tyre perished.**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #9** 2014-07-07 14:20**MOT test number** 256408784189**Result** ✓ Passed

- Notice** Exhaust corroded
- Notice** Front brake pads worn
- Notice** O/s/r sill panel damaged
- Notice** Front discs slightly lipped

MOT #8 2014-07-07 10:51**MOT test number** 846658984165**Result** ✗ Failed

- Notice** Front discs slightly lipped
- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Notice** Exhaust corroded
- Notice** Front brake pads worn
- Fail** Offside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)
- Notice** O/s/r sill panel damaged

MOT #7 2013-07-05 10:37**MOT test number** 295016683185**Result** ✓ Passed**MOT #6** 2012-07-05 10:57**MOT test number** 465897182114**Result** ✓ Passed

**MOT #5** 2011-06-23 09:57**MOT test number** 989304171181**Result** ✓ Passed**Notice** STRONGLY ADVISE: BOTH REAR AND OFFSIDE FRONT TYRES ARE SERIOUSLY CRACKED.**MOT #4** 2010-06-29 11:28**MOT test number** 432970380192**Result** ✓ Passed**MOT #3** 2009-07-14 10:14**MOT test number** 990865399190**Result** ✓ Passed**MOT #2** 2009-07-14 10:14**MOT test number** 340895599196**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #1** 2009-04-03 11:59**MOT test number** 471173799077**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
13 February 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	13 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-04-18
Last registration	2024-01-16
Complete history	See info



Registration #1	2006-04-18	27 mi
Registration #2	2009-04-03	14.954 mi
Registration #3	2009-07-14	15.144 mi
Registration #4	2010-06-29	19.213 mi
Registration #5	2011-06-23	23.215 mi
Registration #6	2012-07-05	26.404 mi
Registration #7	2013-07-05	30.113 mi
Registration #8	2014-07-07	32.979 mi
Registration #9	2014-07-07	32.979 mi
Registration #10	2015-07-06	35.243 mi
Registration #11	2015-07-06	35.243 mi
Registration #12	2016-06-16	36.037 mi
Registration #13	2016-06-16	36.037 mi
Registration #14	2016-06-16	36.037 mi
Registration #15	2016-06-16	36.037 mi
Registration #16	2016-06-16	36.037 mi
Registration #17	2016-06-16	36.037 mi
Registration #18	2016-06-16	36.037 mi
Registration #19	2016-06-16	36.037 mi
Registration #20	2016-06-16	36.037 mi
Registration #21	2016-06-16	36.037 mi
Registration #22	2016-06-16	36.037 mi
Registration #23	2016-06-16	36.037 mi
Registration #24	2016-06-16	36.037 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1245 kg
Max. allowed weight	1832 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LH4G1454817