



report date: 2024-03-28

General information

Make	MINI
Model	ONE CLUBMAN
Colour	Blue
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 3.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 3

Date	2023-06-28
Pictures	0
Listing price	<a href="#">View report</a>

source: carcraft.co.uk

Entry 2


Date	2023-06-24
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2022-04-15
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-16
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	29
Total items failed	6

MOT #12	2024-04-27 08:07
MOT test number	751089439707
Result	✓ Passed
Next expiry date	2025-05-16
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2023-04-26 15:36
MOT test number	238734821110
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #10**

2023-04-24 15:29

**MOT test number**

554962395062

**Result****✗ Failed****Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #9**

2022-05-17 14:20

**MOT test number**

294730308271

**Result****✓ Passed****MOT #8**

2022-05-17 13:14

**MOT test number**

169663903188

**Result****✗ Failed****Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 185/65.15 (5.2.3 (d) (i))

**MOT #7** 2021-06-22 09:03**MOT test number** 667414440996**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #6** 2020-06-22 09:17**MOT test number** 173962632412**Result** ✓ Passed**MOT #5** 2019-05-28 08:39**MOT test number** 303345146205**Result** ✓ Passed**MOT #4** 2018-05-22 08:49**MOT test number** 413390093967**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear boot door opens on its own poss boot switch**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #3** 2017-05-23 15:32**MOT test number** 799370655676**Result** ✓ Passed**Advice** Nearside Rear the tyre has splits on the outer side wall**Advice** Offside Rear the tyre has splits on the outer side wall**MOT #2** 2017-05-23 08:40**MOT test number** 555013035711**Result** ✗ Failed**Advice** Nearside Rear the tyre has splits on the outer side wall**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear the tyre has splits on the outer side wall**MOT #1** 2016-05-24 11:22**MOT test number** 544974310887**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
16 May 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	16 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-05-23
Last registration	2024-04-27
Complete history	<a href="#">See info</a>



Registration #1	2013-05-23	10 mi
Registration #2	2016-05-24	31.006 mi
Registration #3	2017-05-23	38.072 mi
Registration #4	2017-05-23	38.072 mi
Registration #5	2018-05-22	45.215 mi
Registration #6	2019-05-28	55.601 mi
Registration #7	2020-06-22	64.570 mi
Registration #8	2021-06-22	73.720 mi
Registration #9	2022-06-22	82.870 mi
Registration #10	2023-06-22	92.020 mi
Registration #11	2024-06-22	101.170 mi
Registration #12	2025-06-22	110.320 mi
Registration #13	2026-06-22	119.470 mi
Registration #14	2027-06-22	128.620 mi
Registration #15	2028-06-22	137.770 mi
Registration #16	2029-06-22	146.920 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1426 mm
Length	3961 mm
Wheel base	2547 mm
Kerb weight	1140 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Engine number**

A040J471