



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-11-29
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-07
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	37
Total items failed	15

MOT #17	2023-11-08 16:50
MOT test number	194862577904
Result	✓ Passed
Next expiry date	2024-12-07
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #16	2023-11-08 09:48
MOT test number	413498458332
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Road wheel fixing missing (5.2.1 (a) (i))
Fail	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Nearside Obligatory mirror missing (3.3 (a))
Fail	Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Fail	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #15**

2022-12-01 17:07

MOT test number

748125187274

Result

✓ Passed

Advice

Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))

Advice

Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))

MOT #14

2022-12-01 10:28

MOT test number

762058868422

Result

✗ Failed

Advice

Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))

Fail

Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice

Tyre slightly damaged/cracking or perishing both rear (5.2.3 (d) (ii))

MOT #13

2021-12-08 10:00

MOT test number

946175666415

Result

✓ Passed

Advice

Gearbox mounting defective

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12**

2021-02-24 10:55

MOT test number

493632265808

Result

✓ Passed

Advice

Undertrays fitted

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #11

2020-01-30 09:34

MOT test number

330760842629

Result

✓ Passed

Advice

Offside Rear Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))

Minor

Offside Rear Upper Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice

Possible injector blowing further investigation needed

MOT #10

2020-01-29 14:49

MOT test number

116075306061

Result

✗ Failed

Fail

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Offside Rear Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))

Minor

Offside Rear Upper Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Fail

Nearside Rear Anti-roll bar linkage insecurely attached snapped/broken (5.3.3 (a) (i))

Advice

Possible injector blowing further investigation needed

**MOT #9** 2019-02-25 10:03**MOT test number** 699943341033**Result** ✓ Passed**MOT #8** 2019-02-23 11:43**MOT test number** 646837254711**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #7** 2018-02-19 11:35**MOT test number** 444632161829**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 205 50 r17 (4.1.E.1)**MOT #6** 2018-02-19 10:43**MOT test number** 109014627028**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit 205 50 r17 (4.1.E.1)**MOT #5** 2017-03-01 13:44**MOT test number** 302336257083**Result** ✓ Passed**Advice** Both rear tyres worn low on inner edge

**MOT #4** 2017-02-28 12:05**MOT test number** 915849670351**Result** ✗ Failed**Advice** Both rear tyres worn low on inner edge**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Headlamp aim too low Won't adjust (1.8)**Advice** Brake fluid level slightly low**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Fail** Nearside Headlamp aim too low Won't adjust (1.8)**MOT #3** 2015-11-11 10:30**MOT test number** 707627701416**Result** ✓ Passed**Advice** Oil leak**MOT #2** 2014-10-15 14:09**MOT test number** 679718584254**Result** ✓ Passed**Notice** Child seat fitted 2 nearside rear**MOT #1** 2013-11-01 11:39**MOT test number** 485735603416**Result** ✓ Passed**Notice** Both front discs lip & worn



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
7 December 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	7 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-11-12
Last registration	2023-11-08
Complete history	See info



Registration #1	2010-11-12	18 mi
Registration #2	2013-11-01	51.999 mi
Registration #3	2014-10-15	67.311 mi
Registration #4	2015-11-11	80.086 mi
Registration #5	2017-02-28	97.345 mi
Registration #6	2017-03-01	97.345 mi
Registration #7	2018-02-19	110.716 mi
Registration #8	2018-02-19	110.717 mi
Registration #9	2019-02-23	121.174 mi
Registration #10	2019-02-25	121.174 mi
Registration #11	2019-03-20	121.174 mi
Registration #12	2019-03-20	121.174 mi
Registration #13	2019-03-20	121.174 mi
Registration #14	2019-03-20	121.174 mi
Registration #15	2019-03-20	121.174 mi
Registration #16	2019-03-20	121.174 mi
Registration #17	2019-03-20	121.174 mi
Registration #18	2019-03-20	121.174 mi
Registration #19	2019-03-20	121.174 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602