




report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOVANO F3500 L3H1 C/C CDTI
Colour	White
Year of manufacture	2015
Top speed	80 mph
0 - 60 mph	14.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	35.0 mpg
Consumption combined	32.0 mpg
CO2 emission	226 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-08-16
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-11-10
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	19
Total items failed	2

MOT #9	2022-11-11 17:05
MOT test number	628488154718
Result	✓ Passed
Next expiry date	2023-11-10

MOT #8	2022-11-04 09:58
MOT test number	307033466019
Result	✗ Failed

MAJOR Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice All side body markers not working

MAJOR Nearside Front Service brake excessively binding (1.2.1 (f))

MAJOR Offside Rear Position lamp not working (4.2.1 (a) (ii))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Front Service brake excessively fluctuating (1.2.1 (e))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #7** 2021-09-08 07:31**MOT test number** 946796522440**Result** ✓ Passed**MOT #6** 2021-09-03 08:16**MOT test number** 527184780042**Result** ✗ Failed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material Brake Pipe Corroded To Flexi (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #5** 2020-12-24 11:34**MOT test number** 960485995971**Result** ✓ Passed**MOT #4** 2020-12-21 10:32**MOT test number** 897656677586**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))



MOT #3	2019-12-17 13:47
MOT test number	250419654884
Result	✓ Passed

MOT #2	2019-12-11 11:08
MOT test number	687859178003
Result	✗ Failed
MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))	

MOT #1	2018-12-28 10:03
MOT test number	437922847224
Result	✓ Passed
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✗
MOT
Expired:
10 November 2023

Tax status	Valid until 1 September
Days left	124
MOT expiry date	10 November 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 FL65DYD
Plate since	2019-03-29
Current registration	 FL65DYD
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-12-30
Last registration	2022-11-11
Complete history	See info



Registration #1	2015-12-30	21 mi
Registration #2	2018-12-28	89.416 mi
Registration #3	2019-12-11	116.175 mi
Registration #4	2019-12-17	116.179 mi
Registration #5	2020-12-21	136.401 mi
Registration #6	2020-12-24	136.442 mi
Registration #7	2020-12-24	136.442 mi
Registration #8	2020-12-24	136.442 mi
Registration #9	2020-12-24	136.442 mi
Registration #10	2020-12-24	136.442 mi
Registration #11	2020-12-24	136.442 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2350 mm
Length	6418 mm
Kerb weight	1686 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	M9T -C156231 LWL