



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO POP
Colour	Grey
Year of manufacture	2012
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	123 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-18
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	29
Total items failed	5

MOT #13	2024-02-14 10:39
MOT test number	522863679161
Result	✓ Passed
Next expiry date	2025-02-18
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #12	2023-02-16 17:44
MOT test number	162928854595
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2023-02-16 15:54**MOT test number** 933606151958**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #10** 2022-02-09 10:50**MOT test number** 936406840635**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**Advice** Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**MOT #9** 2021-02-19 14:26**MOT test number** 315284178852**Result** ✓ Passed**MOT #8** 2020-12-31 09:04**MOT test number** 999587513259**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Slight play in steering column

**MOT #7**

2020-12-28 17:03

MOT test number

399293548149

Result**✗ Failed****Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))**Advice** Slight play in steering column**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #6**

2020-08-19 07:15

MOT test number

555158569551

Result**✓ Passed****Advice** Rear Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))**MOT #5**

2019-08-23 09:13

MOT test number

349779556661

Result**✓ Passed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #4**

2018-08-24 09:52

MOT test number

631023574238

Result**✓ Passed**

**MOT #3** 2017-08-22 07:41**MOT test number** 569394406222**Result** ✓ Passed

- Advice** Rear exhaust silencer corroded
- Advice** Coolant leak radiator leaking
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2016-09-14 11:09**MOT test number** 542732196090**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Both rear tyre sidewalls slightly deteriorated
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brakes binding slightly

MOT #1 2015-09-23 10:34**MOT test number** 688074519411**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
18 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	18 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-09-29
Last registration	2024-02-14
Complete history	See info



Registration #1	2012-09-29	11 mi
Registration #2	2015-09-23	9.516 mi
Registration #3	2016-09-14	14.930 mi
Registration #4	2017-08-22	19.005 mi
Registration #5	2018-08-24	23.116 mi
Registration #6	2019-08-23	27.210 mi
Registration #7	2020-08-19	29.429 mi
Registration #8	2020-12-28	30.108 mi
Registration #9	2021-05-20	31.277 mi
Registration #10	2021-09-23	32.446 mi
Registration #11	2022-03-26	33.615 mi
Registration #12	2022-07-29	34.784 mi
Registration #13	2023-01-31	35.953 mi
Registration #14	2023-05-24	37.122 mi
Registration #15	2024-02-14	38.291 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	1575 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	6868903