





report date: 2024-03-28

General information

Make	BMW
Model	1 SERIES 116D M SPORT
Colour	Red
Year of manufacture	2013
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2021-01-28

Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-20
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	18
Total items failed	5

MOT #11		2023-11-16 17:16
MOT test	number	958945958763
Result		✓ Passed
Next expi	ry date	2024-11-20
Advice	Offside Play in steering rack inner joint(s)	
Advice	Nearside Front Valve stem slightly damaged perished (5.2.3 (j))	

MOT #10	2023-11-16 10:07	
MOT test number	719825181033	
Result	× Failed	
Advice Offside Play in steering rack inner joint(s)		
Fail Offside Headlamp light source and lamp not compatible LED bulbs fitted to halo	ogen lamp (4.1.4 (c))	
Advice Nearside Front Valve stem slightly damaged perished (5.2.3 (j))		
Fail Nearside Headlamp light source and lamp not compatible LED bulbs fitted to ha	alogen lamp (4.1.4 (c))	
Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))		

CarCheck.co.uk page 3/12



MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Play in steering rack inner joint(s)

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT test number

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge tread low on edge (5.2.3 (e))

Minor

Nearside Rear Tyre obviously under inflated (5.2.3 (l))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

695065445022

Result

Minor Nearside Rear Tyre obviously under inflated (5.2.3 (I))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge tread low on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6

MOT test number

615672594144

Result

Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge Worn on outer edge (5.2.3 (e))

Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge Worn on outer edge (5.2.3 (e))

Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #4	2018-11-06 10:09
MOT test number	697692584907
Result	✓ Passed
MOT #3	2017-11-16 14:10
MOT test number	234018069902
Result	✓ Passed
MOT #2	2017-02-23 12:36
MOT test number	209112107485
Result	✓ Passed
MOT #1	2016-02-23 12:00
MOT test number	158165847368
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	20 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory	
For how long did the current and previous owner(s) have this BMW? How many owners defined the current and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-01
Last registration	2023-11-16
Complete history	See info



Registration #1	2013-03-01	21 mi
Registration #2	2016-02-23	75.597 mi
Registration #3	2017-02-23	82.959 mi
Registration #4	2017-11-16	89.188 mi
Registration #5	2018-11-06	92.718 mi
Registration #6	2020-09-28	100.549 mi
Registration #7	2020-09-28	100.549 mi
Registration #8		0.00 44
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 es
Registration #12		0.074
Registration #13		10.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4324 mm
Wheel base	2690 mm
Kerb weight	1305 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	52 I	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	5 pag	e 12/12

Number of axles 2

Engine number 79058452