



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 D3 SE LUX SOLSTICE
Colour	Red
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-12
Pictures	45
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-12
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	12
Total items failed	0

MOT #11 2023-08-17 10:02

MOT test number 987827676158

Result ✓ Passed

Next expiry date 2024-09-12

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))

Advice Parking brake lever travel is high

MOT #10 2022-09-07 11:48

MOT test number 644063684443

Result ✓ Passed

Advice Nearside Rear Nail in tyre

MOT #9 2021-09-13 08:07

MOT test number 572237999412

Result ✓ Passed

MOT #8 2020-11-24 16:21

MOT test number 207071731051

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2020-11-24 11:06**MOT test number** 488748590694**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2019-06-24 14:27**MOT test number** 408893364106**Result** ✓ Passed**MOT #5** 2019-06-24 10:40**MOT test number** 131210399377**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing inner sidewall (5.2.3 (d) (ii))**DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure 235/40/18 95y (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing inner sidewall (5.2.3 (d) (ii))**MOT #4** 2018-06-20 13:50**MOT test number** 859841771185**Result** ✓ Passed**MOT #3** 2018-06-20 09:25**MOT test number** 674670699565**Result** ✗ Failed**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))



MOT #2	2017-06-21 10:28
MOT test number	709980105603
Result	✓ Passed

MOT #1	2016-06-20 13:30
MOT test number	667372925643
Result	✓ Passed

Advice Front tyres worn on inner edges



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
12 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	12 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	DA13HLR
Plate since	2019-03-29
Current registration	DA13HLR
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-06-27
Last registration	2023-08-17
Complete history	See info



Registration #1	2013-06-27	16 mi
Registration #2	2016-06-20	18.403 mi
Registration #3	2017-06-21	22.233 mi
Registration #4	2018-06-20	25.849 mi
Registration #5	2018-06-20	25.849 mi
Registration #6	2019-06-24	29.055 mi
Registration #7	2019-06-24	29.059 mi
Registration #8	2019-06-24	29.059 mi
Registration #9	2019-06-24	29.059 mi
Registration #10	2019-06-24	29.059 mi
Registration #11	2019-06-24	29.059 mi
Registration #12	2019-06-24	29.059 mi
Registration #13	2019-06-24	29.059 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	2025 mm
Height	1400 mm
Length	4615 mm
Wheel base	2640 mm
Kerb weight	1811 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	1224080
---------------	---------