



HONDA

PEIIZVB

report date: 2024-03-29

General information

Make	HONDA
Model	INSIGHT IMA EX
Colour	Blue
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	120 Nm at 4.500 rpm
Engine capacity	1.339 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	60.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	61.4 mpg
CO2 emission	105 g/km
CO2 label	B



Internet history

Entry 1

Date	2022-06-26
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-09
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	24
Total items failed	3

MOT #12 2023-06-05 09:40

MOT test number 470465400387

Result ✓ Passed

Next expiry date 2024-06-09

- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11 2022-06-08 07:56

MOT test number 837957852512

Result ✓ Passed

- Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10** 2021-05-12 14:21**MOT test number** 327381537775**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2020-06-10 11:27**MOT test number** 418681606464**Result** ✓ Passed**MOT #8** 2019-04-29 15:05**MOT test number** 897716909693**Result** ✓ Passed**MOT #7** 2018-04-30 12:15**MOT test number** 935711754332**Result** ✓ Passed**MOT #6** 2018-04-30 10:15**MOT test number** 929861432899**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #5** 2017-05-15 09:22**MOT test number** 199742362881**Result** ✓ Passed

**MOT #4** 2016-05-27 08:41**MOT test number** 300801535234**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit inner and outer (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit inner and outer (4.1.E.1)**MOT #3** 2016-05-27 08:41**MOT test number** 955434420141**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit inner and outer (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit inner and outer (4.1.E.1)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #2** 2015-05-05 09:34**MOT test number** 218715825452**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** The off side front tyre tread is thinning on the edges/2mm.**Notice** The off side rear tyre tread is thinning on the inner edge/3mm.**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** The near side front tyre tread is thinning on the edges/2mm.**MOT #1** 2014-05-06 09:31**MOT test number** 336846624167**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 June 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	9 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-05-26
Last registration	2023-06-05
Complete history	See info



Registration #1	2011-05-26	21 mi
Registration #2	2014-05-06	22.981 mi
Registration #3	2015-05-05	38.903 mi
Registration #4	2016-05-27	52.028 mi
Registration #5	2016-05-27	52.028 mi
Registration #6	2017-05-15	61.776 mi
Registration #7	2018-04-30	72.800 mi
Registration #8	2019-05-20	85.277 mi
Registration #9	2019-05-20	85.277 mi
Registration #10	2019-05-20	85.277 mi
Registration #11	2019-05-20	85.277 mi
Registration #12	2019-05-20	85.277 mi
Registration #13	2019-05-20	85.277 mi
Registration #14	2019-05-20	85.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 2012079