





report date: 2024-03-29

#### General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TSI
Colour	Black
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	8.7 seconds
Gearbox	7 speed automatic

### Engine & fuel consumption

Power	160 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.790 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	178 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history

#### Entry 1

Date 2021-07-22


Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



SC59MHE report date: 2024-03-29

MOT history

MOT expiry date	2024-08-09
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	22
Total items failed	9

MOT #15	2023-08-10 14:23
MOT test number	591457385719
Result	✓ Passed
Next expiry date	2024-08-09

MOT #14	2022-04-08 11:05
MOT test number	575645858524
Result	<b>✓</b> Passed
Advice Coolant leak	

мот #	<b>13</b> 2022-04-06 09:24
MOT te	292877650875
Result	<b>X</b> Failed
Fail	Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail (ii))	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b)
Advi	Coolant leak
<b>Fail</b> (b) (ii))	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4

MOT #12	2021-02-16 12:14
MOT test number	974117221291
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

427584903088

Result

✓ Passed

Minor

Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Secondary bonnet catch sticking

Advice

Oil leak, but not excessive engine (8.4.1 (a) (i))

Advice

Factory covers fitted obscuring testable items

MOT #10

MOT test number

Result

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

MOT test number

173535252898

Result

Advice Engine covers and undertrays fitted obscuring some components

2018-02-07 10:46

✓ Passed

 MOT #8
 2017-02-21 12:09

 MOT test number
 234494849861

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



(1.1.A.3b)

SC59MHE

report date: 2024-03-29

MOT #7 2016-11-10 11:42 MOT test number 705290389207

Result 

Passed

Advice Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50%

Advice Nearside Rear Direction indicator has light sources not illuminating, but not more than 50%

(1.4.A.2c)

Advice Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

**Advice** Offside Rear Direction indicator has light sources not illuminating, but not more than 50% (1.4.A.2c)

MOT #6 2015-11-10 15:13

**MOT test number** 535494991320

**Result** ✓ Passed

MOT #5 2015-11-10 13:30

**MOT test number** 460791013634

**Result** X Failed

Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Nearside Rear coil spring broken (2.4.C.1a)

**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #4 2014-11-10 17:36

MOT test number 195304614346

**Result** ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3		2013-11-06 10:21
MOT test	number	959670013365
Result		✓ Passed
<b>Advice</b> (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in exce	essive movement
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5	.1i)
<b>Advice</b> (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not resulting in exc	cessive movement
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.	.5.1i)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.	5.1i)

MOT #2	2012-11-12 13:20
MOT test number	115757012302
Result	<b>✓</b> Passed

Result	✓ Passed
MOT #1	2012-11-12 11:58
MOT test number	907347312336
Result	<b>×</b> Failed
Fail Offside Front Windscreen wiper does not clear the windscreen effectively  Advice Offside Rear Rear position lamp(s) has light sources not illuminating, (1.1.A.3b)  Fail Nearside Front Windscreen wiper does not clear the windscreen effective  Fail Nearside Front Headlamp aim too low (1.8)	but not more than 50%

CarCheck.co.uk page 6/13



report date: 2024-03-29

#### Tax & MOT check





Tax status	Expired at 31 January 2024
Days left	89 days too late
MOT expiry date	9 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29


#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this VOLKSWAGEN had different number plates. mber of plates -More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-01-29
Last registration	2023-08-10
Complete history	See info



Registration #1	2010-01-29	29 mi
Registration #2	2012-11-12	22.133 mi
Registration #3	2012-11-12	22.133 mi
Registration #4	2013-11-06	34.202 mi
Registration #5	2014-11-10	47.836 mi
Registration #6	2015-11-10	60.788 mi
Registration #7	2015-11-10	60.788 mi
Registration #8	2016-11-10	73.786 mi
Registration #9	2017-02-21	74.603 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.177 au
Registration #17		11.177 es

More info >

CarCheck.co.uk page 12/13



SC59MHE report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



### Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1474 kg
Max. allowed weight	2150 kg

### Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
CarChaeleeaule	naga 12/12

CarCheck.co.uk page 13/13

Number of seats	5
Number of axles	2
Engine number	BZB 108515