



report date: 2024-03-28

General information

| | |
|---------------------|----------------------|
| Make | VAUXHALL |
| Model | ANTARA EXCLUSIV CDTI |
| Colour | Black |
| Year of manufacture | 2010 |
| Top speed | 110 mph |
| 0 - 60 mph | 12.8 seconds |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 320 Nm at 2.000 rpm |
| Engine capacity | 1.991 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 25.9 mpg |
| Consumption extra urban | 38.7 mpg |
| Consumption combined | 32.8 mpg |
| CO2 emission | 225 g/km |
| CO2 label | K |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-23 |
| Pictures | 2 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-18 |
| MOT pass rate | 69 % |
| MOT passed | 11 |
| Failed MOT tests | 5 |
| Total advice items | 12 |
| Total items failed | 15 |

| | |
|------------------|--|
| MOT #16 | 2023-09-22 13:27 |
| MOT test number | 424923711023 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-18 |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge 2mm and 1mm edge bald (5.2.3 (e)) |

| | |
|-----------------|--|
| MOT #15 | 2022-10-19 16:08 |
| MOT test number | 179147581201 |
| Result | ✓ Passed |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

**MOT #14** 2022-10-19 09:48**MOT test number** 685292493284**Result** ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Brake lever has insufficient reserve travel (1.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

MOT #13 2021-12-14 14:25**MOT test number** 154719874455**Result** ✓ Passed**MOT #12** 2021-12-14 09:48**MOT test number** 325229633481**Result** ✗ Failed

- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Suspension arm insecurely attached (5.3.3 (a) (i))
- Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #11** 2021-02-04 17:41**MOT test number** 170816457913**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-06-28 12:02**MOT test number** 836899628906**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**MOT #9** 2019-06-27 13:53**MOT test number** 864644499761**Result** ✗ Failed**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Brake fluid contaminated (1.8 (a))**Fail** Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Advice** Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**MOT #8** 2018-06-19 10:17**MOT test number** 757092947035**Result** ✓ Passed

**MOT #7** 2017-06-15 08:53**MOT test number** 264426195795**Result** ✓ Passed**Advice** Rear Nail in tyre both**MOT #6** 2016-07-14 10:01**MOT test number** 489798241310**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-07-02 15:11**MOT test number** 836533985107**Result** ✓ Passed**MOT #4** 2015-07-02 15:11**MOT test number** 318113185111**Result** ✗ Failed**Pass with rectification** Headlamp aim too low (1.8)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2014-07-05 09:56**MOT test number** 477846584184**Result** ✓ Passed**MOT #2** 2013-07-15 12:16**MOT test number** 165446693147**Result** ✓ Passed



| | |
|-----------------|--|
| MOT #1 | 2013-07-08 14:50 |
| MOT test number | 416959783165 |
| Result | ✗ Failed |
| Fail | Front Headlamp cleaning device inoperative (1.7.2) |



Tax & MOT check

X

Untaxed

Tax expired:
31 August 2023

✓

MOT

Expires:
18 October 2024

| | |
|------------------|---------------------------------|
| Tax status | Expired at 31 August 2023 |
| Days left | 241 days too late |
| MOT expiry date | 18 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|------------|------------|
| XXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX | XXXXXXXXXX |
| XXXXXXXXXX | XXXXXXXXXX |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  RE10GY |
| Plate since | 2024-03-28 |
| Current registration |  RE10GY |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | |
|-------------------|--|
| Finance company | |
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2010-06-24 |
| Last registration | 2023-09-22 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-06-24 | 27 mi |
| Registration #2 | 2013-07-08 | 47.625 mi |
| Registration #3 | 2013-07-15 | 47.772 mi |
| Registration #4 | 2014-07-05 | 60.893 mi |
| Registration #5 | 2015-07-02 | 66.832 mi |
| Registration #6 | 2016-07-14 | 73.427 mi |
| Registration #7 | 2017-06-15 | 77.092 mi |
| Registration #8 | 2018-06-19 | 81.578 mi |
| Registration #9 | 2019-06-27 | 86.885 mi |
| Registration #10 | 2020-06-27 | 91.277 mi |
| Registration #11 | 2021-06-27 | 95.677 mi |
| Registration #12 | 2022-06-27 | 100.077 mi |
| Registration #13 | 2023-06-27 | 104.477 mi |
| Registration #14 | 2024-06-27 | 108.877 mi |
| Registration #15 | 2025-06-27 | 113.277 mi |
| Registration #16 | 2026-06-27 | 117.677 mi |
| Registration #17 | 2027-06-27 | 122.077 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 95% |
| Children | 84% |
| Pedestrian | 46% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2085 mm |
| Height | 1747 mm |
| Length | 4575 mm |
| Wheel base | 2707 mm |
| Kerb weight | 1812 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|-----------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 1297938K |