




report date: 2024-03-28

General information

Make	KIA
Model	PICANTO SR7
Colour	White
Year of manufacture	2015
Top speed	98 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	95 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 2


Date	2021-06-23
Pictures	50
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-22
Pictures	65
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-26
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	12
Total items failed	0

MOT #8	2023-08-26 11:16
MOT test number	124291512139
Result	✓ Passed
Next expiry date	2024-08-26

MOT #7	2022-08-27 12:16
MOT test number	147703283757
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge o/s and n/s (5.2.3 (e))

MOT #6	2022-08-27 11:06
MOT test number	990271152499
Result	✗ Failed
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Front Tyre worn close to legal limit/worn on edge o/s and n/s (5.2.3 (e))
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #5	2021-06-28 15:34
MOT test number	156638171068
Result	✓ Passed

**MOT #4** 2020-12-23 10:40**MOT test number** 808015561880**Result** ✓ Passed**MOT #3** 2019-12-20 14:35**MOT test number** 421505122622**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2019-12-19 10:55**MOT test number** 315417408926**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**DANGEROUS** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #1** 2018-12-20 11:46**MOT test number** 576802857620**Result** ✓ Passed**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
26 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	26 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	SJ65MKW
Plate since	2024-03-28
Current registration	SJ65MKW
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-12-31
Last registration	2023-08-26
Complete history	See info



Registration #1	2015-12-31	21 mi
Registration #2	2018-12-20	32.880 mi
Registration #3	2019-12-19	46.243 mi
Registration #4	2019-12-20	46.243 mi
Registration #5	2020-12-23	57.109 mi
Registration #6	2021-01-01	58.000 mi
Registration #7	2021-01-01	58.000 mi
Registration #8	2021-01-01	58.000 mi
Registration #9	2021-01-01	58.000 mi
Registration #10	2021-01-01	58.000 mi
Registration #11	2023-08-26	58.000 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	83%
Pedestrian	47%
Safety systems	43%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1595 mm
Height	1480 mm
Length	3595 mm
Wheel base	2385 mm
Kerb weight	1039 kg
Max. allowed weight	1400 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G3LAFP115250