



report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO JTD DYNAMIC (120BHP)
Colour	Red
Year of manufacture	2006
Top speed	121 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	279 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-14
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-18
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	45
Total items failed	0

MOT #19	2024-01-19 14:20
MOT test number	365771215755
Result	✓ Passed
Next expiry date	2025-01-18

MOT #18	2024-01-16 13:23
MOT test number	966029935508
Result	✗ Failed
MAJOR Nearside Front Service brake excessively binding (1.2.1 (f))	

MOT #17	2023-01-16 16:09
MOT test number	476092257907
Result	✓ Passed

MOT #16	2022-01-14 11:09
MOT test number	973231864689
Result	✓ Passed



MOT #152021-01-14 12:25

MOT test number987316057288

Result

Passed

- Advice

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice

Brake pipe covers fitted
- Advice

Nearside rear wheel rim distorted
- Advice

Rear Passenger seat(s) missing at time of test all
- Advice

Wear offside rear "D" bush
- Advice

Under trays fitted

**MOT #14**

2021-01-07 11:05

MOT test number

668016078644

Result**✗ Failed**

- Advice** Brake pipe covers fitted
- Advice** Rear Passenger seat(s) missing at time of test all
- Advice** Nearside rear wheel rim distorted
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Nearside Obligatory mirror insecure centre missing (3.3 (b) (ii))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Wear offside rear "D" bush
- Advice** Under trays fitted
- MAJOR** Rear Direction indicator adversely affected by the operation of another lamp both (4.4.3 (b))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Front Service brake excessively fluctuating both (1.2.1 (e))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Wear and pitting front discs

MOT #13

2020-01-06 11:02

MOT test number

492054609027

Result**✓ Passed**

- Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened On both sides of vehicle (1.1.14 (a) (ii))
- Advice** Nearside Door mirror assembly repaired with gaffer tape
- Advice** Rear seats folded down not allowing a full inspection of rear seat belts

**MOT #12** 2018-12-05 11:15**MOT test number** 945050434615**Result** Passed**MOT #11** 2018-12-03 11:29**MOT test number** 741710200361**Result** Failed**MAJOR** Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**MAJOR** Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #10** 2018-02-19 12:04**MOT test number** 850722283812**Result** Passed**Advice** Nearside Rear Shock absorber has a slightly worn bush top bush (2.7.4)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Shock absorber has a slightly worn bush top bush (2.7.4)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2017-02-28 17:05**MOT test number** 207344180663**Result** Passed**MOT #8** 2016-03-03 11:30**MOT test number** 585341202299**Result** Passed

**MOT #7** 2015-03-04 16:35**MOT test number** 268963565044**Result** ✓ Passed

- Notice** Nearside rear brake binding slightly
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Shock absorber has a slightly worn bush (2.7.4)
- Notice** Nearside rear tyre wearing on outer edge
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #6 2014-10-06 09:30**MOT test number** 548579474294**Result** ✓ Passed

- Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)

MOT #5 2013-09-10 14:21**MOT test number** 128163653245**Result** ✓ Passed

- Advice** Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

MOT #4 2012-10-05 10:57**MOT test number** 129459472254**Result** ✓ Passed



MOT #3	2011-10-07 11:32
MOT test number	798580681262
Result	✓ Passed
Advice	Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
Advice	Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

MOT #2	2010-10-12 12:56
MOT test number	440045380251
Result	✓ Passed

MOT #1	2009-10-23 09:20
MOT test number	374586799255
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
18 January 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	18 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-10-31
Last registration	2024-01-19
Complete history	See info



Registration #1	2006-10-31	26 mi
Registration #2	2009-10-23	12.755 mi
Registration #3	2010-10-12	19.252 mi
Registration #4	2011-10-07	25.307 mi
Registration #5	2012-10-05	30.590 mi
Registration #6	2013-09-10	36.880 mi
Registration #7	2014-10-06	42.715 mi
Registration #8	2015-03-04	44.049 mi
Registration #9	2016-03-03	56.027 mi
Registration #10	2017-02-28	62.883 mi
Registration #11	2018-02-19	70.006 mi
Registration #12	2019-01-20	75.377 mi
Registration #13	2019-01-20	75.377 mi
Registration #14	2019-01-20	75.377 mi
Registration #15	2019-01-20	75.377 mi
Registration #16	2019-01-20	75.377 mi
Registration #17	2019-01-20	75.377 mi
Registration #18	2019-01-20	75.377 mi
Registration #19	2019-01-20	75.377 mi
Registration #20	2019-01-20	75.377 mi
Registration #21	2019-01-20	75.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1775 mm
Height	1597 mm
Length	4756 mm
Wheel base	2700 mm
Kerb weight	1520 kg
Max. allowed weight	3540 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4898957