





report date: 2024-03-29

## General information

Make	BMW
Model	X5 D SE 5STR
Colour	Black
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	235 BHP
Max. torque	520 Nm at 2.750 rpm
Engine capacity	2.497 сс
Cylinders	6
Fuel type	Diesel
Consumption city	25.0 mpg
Consumption extra urban	39.2 mpg
Consumption combined	32.5 mpg
CO2 emission	231 g/km
CO2 label	L



CarCheck.co.uk page 1/14



## Internet history

## Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-04-02
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	29
Total items failed	14

MOT #20		2023-04-03 11:40
MOT test	number	628496161638
Result		✓ Passed
Next expi	ry date	2024-04-02
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in exc	cessive movement (5.3.4
(a) (i))		
Advice	Offside Rear Parking brake requires adjustment	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excess	ssive movement (5.3.4 (a)
(i))		

MOT #19	2022-02-11 11:49
MOT test number	847821418784
Result	✓ Passed
MOT #18	2021-02-01 13:49
MOT test number	627100225768
Result	✓ Passed

CarCheck.co.uk page 3/14



YE07AHX

report date: 2024-03-29

 MOT #17
 2020-02-15 13:47

 MOT test number
 266172066598

 Result
 ✓ Passed

 MOT #16
 2020-01-11 11:59

 MOT test number
 601197366566

 Result
 ✓ Passed

 Advice
 Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15** 2020-01-07 09:31 **MOT** test number 945280932077 Result × Failed Fail Offside Front Headlamp aim too low (4.1.2 (a)) Fail Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i)) Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii)) Fail Nearside Front Headlamp aim too low (4.1.2 (a)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Fail Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

MOT #14

MOT test number

Result

Advice Nearside Rear inner lamp not working

2019-01-18 17:25

382149843819

✓ Passed

CarCheck.co.uk page 4/14



MOT #13 2019-01-17 12:20

**MOT test number** 329251484527

**Result** X Failed

Fail Nearside Headlamp aim too low (4.1.2 (a))

**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Nearside Rear inner lamp not working

Fail Offside Headlamp aim too low (4.1.2 (a))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #12** 2017-10-19 08:26

**MOT test number** 958357804485

Result \( \sqrt{Passed} \)

**Advice** Oil leak gearbox area

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Offside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)

**MOT #11** 2017-10-06 11:16

**MOT test number** 438748565394

Result × Failed

**Fail** Offside Front coil spring broken (2.4.C.1a)

Advice Offside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)

Fail Offside Rear Rear fog lamp not working (1.3.2b)

Advice Oil leak gearbox area


**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 5/14



YE07AHX

report date: 2024-03-29



MOT #9	2016-04-15 10:26
MOT test number	428085397767
Result	<b>×</b> Failed
Fail Offside Front coil spring broken (2.4.C.1a)	
Advice Under trays fitted restricting inspection	
Fail Nearside Registration plate lamp not working (1.1.C.1d)	
Fail Nearside Front coil spring broken (2.4.C.1a)	
Advice Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)	
Advice Engine covers fitted restricting inspection	

MOT #8	2015-04-21 09:38
MOT test number	509541515186
Result	✓ Passed
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #7	2014-04-11 09:01
MOT test number	996901604103
Result	<b>✓</b> Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/14



MOT #6 2013-04-12 16:19

**MOT test number** 879312703198

Result \rightarrow Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Rear fog lamp has light sources not illuminating, but not more than 50% (1.3.2b)

MOT #5 2012-04-12 12:25

**MOT test number** 207063402471

**Result** ✓ Passed

MOT #4 2011-04-20 17:21

**MOT test number** 627360711188

MOT #3 2010-05-27 17:33

MOT test number 783397340198

Result \( \sqrt{Passed} \)

MOT #2 2010-05-27 17:23

MOT test number 462677340137

Result X Failed

**Notice** O/s rear tyre is worn badly on inner edge

**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

**MOT #1** 2009-05-18 16:07

**MOT test number** 493828739173

**Result** ✓ Passed

**Notice** Nearside rear tyre bald on inner edge.

CarCheck.co.uk page 7/14



## Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	2 April 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 8/14



YE07AHX

report date: 2024-03-29

### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

Owner History		
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I		ve?
**************************************		
***************************************		
THE PROPERTY OF THE PROPERTY O		
********		
***************************************		
	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		9
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-04-26
Last registration	2023-04-03
Complete history	See info



Registration #1	2007-04-26	10 mi
Registration #2	2009-05-18	22.114 mi
Registration #3	2010-05-27	27.647 mi
Registration #4	2010-05-27	27.647 mi
Registration #5	2011-04-20	34.219 mi
Registration #6	2012-04-12	38.592 mi
Registration #7	2013-04-12	43.297 mi
Registration #8	2014-04-11	47.388 mi
Registration #9	2015-04-21	57.436 mi
Registration #10	2016-04-15	74.362 mi
Registration #11	2016-04-25	74.411 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 13/14



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1994 mm
Height	1764 mm
Length	4851 mm
Wheel base	2933 mm
Kerb weight	2180 kg
Max. allowed weight	2955 kg

# Additional information

Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14