



Mercedes-Benz




report date: 2024-03-28

General information

| | |
|---------------------|-------------------------------|
| Make | MERCEDES-BENZ |
| Model | A A 200 AMG LINE PREMIUM PLUS |
| Colour | White |
| Year of manufacture | 2019 |
| Top speed | 140 mph |
| 0 - 100 km/h | 8.2 seconds |
| 0 - 60 mph | 8.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 120 kW / 163 HP / 161 BHP |
| Max. torque | 250 Nm at 1.620 rpm |
| Engine capacity | 1.332 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 34.9 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 2.8 mpg |
| CO2 emission | 136 g/km |
| CO2 label | E |





Internet history

Entry 2

| | |
|----------|------------|
| Date | 2023-12-15 |
| Pictures | 8 |



source: g3remarketing.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-06-06 |
| Pictures | 27 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-03 |
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 8 |
| Total items failed | 2 |

MOT #4 2024-03-04 13:58

MOT test number 686345123903

Result ✓ Passed

Next expiry date 2025-03-03

Advice Front chip in windscreen**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #3 2023-02-23 15:42

MOT test number 126937793933

Result ✓ Passed**Advice** Brake disc worn, but not excessively both fronts (1.1.14 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #2 2023-02-23 10:15

MOT test number 731046618169

Result ✗ Failed**Fail** Brake disc significantly and obviously worn both rears (1.1.14 (a) (i))**Fail** Brake pad(s) less than 1.5 mm thick both rears (1.1.13 (a) (ii))**Advice** Brake disc worn, but not excessively both fronts (1.1.14 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



| | |
|-----------------|---|
| MOT #1 | 2022-03-04 10:51 |
| MOT test number | 546278702807 |
| Result | ✓ Passed |
| Advice | Items removed from driver's view prior to test air fresheners from mirror |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
3 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 3 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | H |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  YK19KRU |
| Plate since | 2019-03-28 |
| Current registration |  YK19KRU |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 6 |
| First mileage registration | 2019-04-24 |
| Last registration | 2024-03-04 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2019-04-24 | 16 mi |
| Registration #2 | 2022-03-04 | 33.436 mi |
| Registration #3 | 2022-03-04 | 33.436 mi |
| Registration #4 | 2022-03-04 | 33.436 mi |
| Registration #5 | 2022-03-04 | 33.436 mi |
| Registration #6 | 2022-03-04 | 33.436 mi |

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 96% |
| Children | 91% |
| Pedestrian | 92% |
| Safety systems | 75% |
| Overall rating | 90% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1796 mm |
| Height | 1440 mm |
| Length | 4419 mm |
| Wheel base | 2729 mm |
| Kerb weight | 1355 kg |
| Max. allowed weight | 1870 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 43 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |

| | |
|-----------------|----------------|
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 28291480096021 |