



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D4 SE LUX
Colour	Blue
Year of manufacture	2012
Top speed	134 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg
CO2 emission	142 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-10-29
Pictures	20
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2024-07-06
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	12
Total items failed	4

## MOT #10 2023-06-28 06:39

MOT test number 188748851635

Result ✓ Passed

Next expiry date 2024-07-06

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge 235/45/17yxzl (5.2.3 (e))

## MOT #9 2023-06-23 09:17

MOT test number 834347937303

Result ✗ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge 235/45/17yxzl (5.2.3 (e))

**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2022-07-07 09:06**MOT test number** 364342910710**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Nail in tyre**MOT #7** 2021-05-03 08:27**MOT test number** 100354775048**Result** ✓ Passed**MOT #6** 2020-04-26 07:58**MOT test number** 788726073518**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view small chip in front windscreen (3.2 (a) (i))**MOT #5** 2019-05-04 12:28**MOT test number** 610116510634**Result** ✓ Passed**MOT #4** 2018-05-25 17:05**MOT test number** 165307724179**Result** ✓ Passed**MOT #3** 2017-06-25 11:18**MOT test number** 614353782324**Result** ✓ Passed



MOT #2	2016-07-03 08:50
MOT test number	151109567867
Result	✓ Passed

MOT #1	2015-07-21 10:13
MOT test number	145102105267
Result	✓ Passed

- Advice

Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice

Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
6 July 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	6 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>KV62NKL</b>
Plate since	2019-09-29
Current registration	<b>KV62NKL</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-09-14
Last registration	2023-06-28
Complete history	<a href="#">See info</a>



Registration #1	2012-09-14	21 mi
Registration #2	2015-07-21	64.094 mi
Registration #3	2016-07-03	70.308 mi
Registration #4	2017-06-25	79.961 mi
Registration #5	2018-05-25	89.988 mi
Registration #6	2019-05-04	97.482 mi
Registration #7	2020-05-20	105.277 mi
Registration #8	2021-05-20	113.277 mi
Registration #9	2022-05-20	121.277 mi
Registration #10	2023-05-20	129.277 mi
Registration #11	2024-05-20	137.277 mi
Registration #12	2025-05-20	145.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1628 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	1208964
---------------	---------