





report date: 2024-03-28

General information

Make	KIA
Model	PROCEED PRO CEED GT
Colour	Black
Year of manufacture	2013
Top speed	143 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	201 BHP
Max. torque	265 Nm at 4.500 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	46.3 mpg
Consumption combined	38.2 mpg
CO2 emission	171 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2021-07-15

Pictures 2

Listing price <u>View report</u>





source: autotrader.co.uk

Entry 1

Date	2021-07-15
Pictures	2
Listing price	View report





source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2024-05-13
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	16
Total items failed	2

MOT #11	2023-04-22 09:44
MOT test number	182066075117
Result	✓ Passed
Next expiry date	2024-05-13
Advice Front and rear fog lamp switch faulty	

MOT #10	2022-05-14 09:04
MOT test number	784234085201
Result	✓ Passed
MOT #9	2021-05-05 08:36
MOT test number	377334260753
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

, y to the table of table o	
MOT #8	2020-05-14 09:55
MOT test number	199248630280
Result	✓ Passed
MOT #7	2019-05-21 15:03
MOT test number	731135086664
Result	✓ Passed

CarCheck.co.uk page 3/12



(8.3.1d)

WR63WZE

report date: 2024-03-28

	9-05-08 14:25
MOT test number	92544538554

Result ✓ Passed

MOT #5 2018-11-15 12:50

MOT test number 231971355282

Result
✓ Passed

MOT #4 2017-11-18 09:47

MOT test number 872931669937

Result Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Tpms light on dash

Advice Nearside Front Tyre worn close to the legal limit worn on edges aswell (4.1.E.1)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' small crack on n/s

Advice Offside Front Tyre worn close to the legal limit worn on edges aswell (4.1.E.1)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 4/12



Result

WR63WZE

report date: 2024-03-28

× Failed

MOT #3 2017-11-18 09:47 181606873648 **MOT** test number Result × Failed **Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a) Pass with rectification Offside Rear Registration plate lamp not working (1.1.C.1d) **Advice** Offside Front Tyre worn close to the legal limit worn on edges aswell (4.1.E.1) Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Tpms light on dash Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' small crack on n/s (8.3.1d)Advice Nearside Front Tyre worn close to the legal limit worn on edges aswell (4.1.E.1) **Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

 MOT #2
 2016-11-19 09:07

 MOT test number
 496035829042

 Result
 ✓ Passed

 MOT #1
 2016-11-19 09:07

 MOT test number
 654713708887

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	13 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



WR63WZE report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	UK NIE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-11-28
Last registration	2023-04-22
Complete history	See info



Registration #1	2013-11-28	14 mi
Registration #2	2016-11-19	31.979 mi
Registration #3	2016-11-19	31.979 mi
Registration #4	2017-11-18	39.101 mi
Registration #5	2017-11-18	39.101 mi
Registration #6	2018-11-15	45.650 mi
Registration #7	2019-05-08	50.171 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		11.777 44

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1430 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1448 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 12/

Number of axles 2

Engine number G4FJDS507408