



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI STYLE
Colour	Black
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-17
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-19
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	70
Total items failed	16

MOT #16	2024-03-04 10:45
MOT test number	647105920491
Result	✓ Passed
Next expiry date	2025-03-19
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2024-03-04 10:45
MOT test number	227338466991
Result	✗ Failed
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14	2023-03-11 13:59
MOT test number	551321047730
Result	✓ Passed

**MOT #13**

2023-03-11 09:14

MOT test number

699163854720

Result**✗ Failed**

- Fail** Offside Headlamp aim unable to be tested BULB NOT WORKING (4.1.2 (b))
- Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge BOTH TYRES ADVISE REPLACE ASAP (5.2.3 (e))
- Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 215/50R17 (5.2.3 (e))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** COOLANT TANK EMPTY
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12

2022-03-16 17:13

MOT test number

575314309540

Result**✓ Passed**

**MOT #11**

2021-03-10 08:43

MOT test number

388431666438

Result

✓ Passed

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing Cracking in tread 215/50 17 W (5.2.3 (d) (ii))

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice

Undertrays fitted, Obscuring the view of some components.

Advice

Offside Rear Tyre slightly damaged/cracking or perishing Cracking in tread 215/50 17 W (5.2.3 (d) (ii))

Advice

Brake pipe corroded, covered in grease or other material All coated (1.1.11 (c))

MOT #10

2021-03-09 17:21

MOT test number

601132199846

Result

✗ Failed

Advice

Undertrays fitted, Obscuring the view of some components.

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing Cracking in tread 215/50 17 W (5.2.3 (d) (ii))

Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail

Offside Front Seat belt buckle not functioning as intended (7.1.2 (d))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing Cracking in tread 215/50 17 W (5.2.3 (d) (ii))

Advice

Brake pipe corroded, covered in grease or other material All coated (1.1.11 (c))



MOT #92020-03-10 13:24

MOT test number265709539060

Result

✓ Passed

- Advice

Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge WEARING ON EDGE (5.2.3 (e))
- Advice

Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge AT 3MM WEARING INNER EDGE (5.2.3 (e))
- Advice

Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #8** 2020-03-05 16:17**MOT test number** 672108422165**Result** ✗ Failed

- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge WEARING ON EDGE (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Play in steering rack inner joint(s) EXCESSIVE PLAY
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge AT 3MM WEARING INNER EDGE (5.2.3 (e))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Service brake excessively binding (1.2.1 (f))

MOT #7 2019-02-27 12:24**MOT test number** 994038927852**Result** ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing n/s/r tyre cracking (5.2.3 (d) (ii))
- Advice** Child seat fitted in back
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing o/s/r tyre cracking (5.2.3 (d) (ii))
- Advice** Offside Rear o/s/r lower control arm bolt vibration rubber perished/ no longer seated
- Advice** Offside Rear o/s/r driver pass door damaged

**MOT #6**

2019-02-26 10:53

MOT test number

755128763046

Result**✗ Failed**

- Advice** Offside Rear o/s/r driver pass door damaged
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing o/s/r tyre cracking (5.2.3 (d) (ii))
- Fail** Offside Front Steering linkage ball joint has excessive play o/s/f inner rack arm has excessive play (2.1.3 (b) (i))
- Advice** Child seat fitted in back
- Advice** Offside Rear o/s/r lower control arm bolt vibration rubber perished/ no longer seated
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing n/s/r tyre cracking (5.2.3 (d) (ii))
- Fail** Nearside Rear Service brake excessively binding n/s/r brake binding fluctuation on brake roller test + squeals when rotated (1.2.1 (f))

MOT #5

2018-03-02 12:13

MOT test number

853521765361

Result**✓ Passed**

- Advice** Registration plate deteriorated but not likely to be misread rear reg plate (6.3.1d)
- Advice** Emissions not detected on smoke test too clean
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear tyre badly worn on inner edges(215 50 17)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear tyre badly worn on inner edges nearly showing cords

**MOT #4** 2018-03-02 11:14**MOT test number** 350076494475**Result** ✗ Failed

- Advice** Offside Rear tyre badly worn on inner edges nearly showing cords
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Headlamp aim too low and too far to the left. (1.8)
- Advice** Emissions not detected on smoke test too clean
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Registration plate deteriorated but not likely to be misread rear reg plate (6.3.1d)
- Advice** Nearside Rear tyre badly worn on inner edges(215 50 17)

MOT #3 2017-02-23 12:53**MOT test number** 952781313908**Result** ✓ Passed

- Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)
- Advice** Nearside Front tyre has some sidewall damage

MOT #2 2016-03-12 11:40**MOT test number** 496337573205**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** N/s/f tyre 3mm
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Both front tyres worn inner and outer edge
- Advice** N/s/f tyre has cuts to side wall but not to cords



MOT #1

2016-03-09 09:51

MOT test number

291510027890

Result

✗ Failed

Advice

Both front tyres worn inner and outer edge

Advice

N/s/f tyre has cuts to side wall but not to cords

Fail

Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

Advice

Rear Brake pad(s) wearing thin (3.5.1g)

Advice

N/s/f tyre 3mm

Advice

Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
19 March 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	19 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EX13XJC
Plate since	2019-03-28
Current registration	EX13XJC
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2013-03-20
Last registration	2024-03-04
Complete history	See info



Registration #1	2013-03-20	28 mi
Registration #2	2016-03-09	52.896 mi
Registration #3	2016-03-12	53.047 mi
Registration #4	2017-02-23	67.146 mi
Registration #5	2018-03-02	86.627 mi
Registration #6	2018-03-02	86.627 mi
Registration #7	2019-02-26	100.001 mi
Registration #8	2019-02-27	100.001 mi
Registration #9	2020-03-05	111.113 mi
Registration #10	2020-03-05	111.113 mi
Registration #11	2020-03-05	111.113 mi
Registration #12	2020-03-05	111.113 mi
Registration #13	2020-03-05	111.113 mi
Registration #14	2020-03-05	111.113 mi
Registration #15	2020-03-05	111.113 mi
Registration #16	2020-03-05	111.113 mi
Registration #17	2020-03-05	111.113 mi
Registration #18	2020-03-05	111.113 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1659 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDDU275854