



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 S S40
Colour	Silver
Year of manufacture	2008
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-03-12
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-23
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	11
Total items failed	7

MOT #17 2024-01-24 11:52

MOT test number 834183155321

Result ✓ Passed

Next expiry date 2025-01-23

Advice Offside Front Tyre worn close to legal limit/worn on edge worn low and badly cracked (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn low and badly cracked (5.2.3 (e))

MOT #16 2022-12-05 12:16

MOT test number 471898259948

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2021-11-25 15:49

MOT test number 582838159685

Result ✓ Passed

**MOT #14** 2021-11-18 11:59**MOT test number** 634807913661**Result** ✗ Failed**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #13** 2020-12-07 12:47**MOT test number** 759693936971**Result** ✓ Passed**MOT #12** 2020-12-07 12:47**MOT test number** 418672568928**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Offside Front Outline marker lamp not working (4.2.1 (a) (ii))**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #11** 2019-05-22 09:56**MOT test number** 373297977105**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #10** 2018-06-04 12:35**MOT test number** 429646774166**Result** ✓ Passed

**MOT #9** 2018-06-04 12:35**MOT test number** 885281572695**Result** ✗ Failed**Pass with rectification** Offside Front Steering locking device ineffective (2.1.3 (d))**MOT #8** 2017-06-12 12:12**MOT test number** 624125321507**Result** ✓ Passed**MOT #7** 2016-06-10 10:12**MOT test number** 263524695626**Result** ✓ Passed**MOT #6** 2015-06-09 13:15**MOT test number** 576500865174**Result** ✓ Passed**MOT #5** 2014-05-27 11:15**MOT test number** 606627144187**Result** ✓ Passed**MOT #4** 2013-05-29 12:33**MOT test number** 456799643137**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-05-21 14:31**MOT test number** 858962942164**Result** ✓ Passed



MOT #2	2012-05-21 13:02
MOT test number	875542342145
Result	✗ Failed
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #1	2011-05-11 13:06
MOT test number	158811231172
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Front front brake grabbing slightly (3.7.A.2b)
Advice	Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
23 January 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-06-10
Last registration	2024-01-24
Complete history	See info



Registration #1	2008-06-10	17 mi
Registration #2	2011-05-11	33.771 mi
Registration #3	2012-05-21	39.090 mi
Registration #4	2012-05-21	39.090 mi
Registration #5	2013-05-29	45.155 mi
Registration #6	2014-05-27	50.465 mi
Registration #7	2015-06-09	55.396 mi
Registration #8	2016-06-10	60.974 mi
Registration #9	2017-06-12	67.098 mi
Registration #10	2018-06-04	72.094 mi
Registration #11	2019-06-04	75.000 mi
Registration #12	2020-06-04	75.000 mi
Registration #13	2021-06-04	75.000 mi
Registration #14	2022-06-04	75.000 mi
Registration #15	2023-06-04	75.000 mi
Registration #16	2024-01-24	75.000 mi
Registration #17	2024-01-24	75.000 mi
Registration #18	2024-01-24	75.000 mi
Registration #19	2024-01-24	75.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	131943
---------------	--------