



report date: 2024-03-29

General information

| | |
|---------------------|---------------------------------|
| Make | CITROEN |
| Model | C4 CACTUS PURETECH FEEL EDITION |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 106 mph |
| 0 - 60 mph | 13.1 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 80 BHP |
| Max. torque | 118 Nm at 2.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 108 g/km |
| CO2 label | B |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-11-09 |
| Pictures | 24 |
| Listing price | View report |



source: [yesauto.com](#)

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2024-08-06 |
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 3 |
| Total items failed | 3 |

| | |
|-------------------------|------------------|
| MOT #6 | 2023-08-07 14:46 |
| MOT test number | 387491579230 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-06 |

| | |
|---|------------------|
| MOT #5 | 2023-08-02 10:06 |
| MOT test number | 163883463936 |
| Result | ✗ Failed |
| <div>Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement ARM Rear bush cracking - deteriorating. (5.3.4 (a) (i))</div> <div>Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))</div> <div>Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement ARM Rear bush cracking - deteriorating. (5.3.4 (a) (i))</div> <div>Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))</div> | |

| | |
|---|------------------|
| MOT #4 | 2023-01-12 11:34 |
| MOT test number | 721162873829 |
| Result | ✓ Passed |
| <div>Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))</div> | |

| | |
|------------------------|------------------|
| MOT #3 | 2022-01-14 22:02 |
| MOT test number | 691339738630 |
| Result | ✓ Passed |



| | |
|--|------------------|
| MOT #2 | 2022-01-12 11:11 |
| MOT test number | 836390783339 |
| Result | ✗ Failed |
| <div><div>Fail</div>Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))</div> | |

| | |
|-----------------|------------------|
| MOT #1 | 2021-06-08 10:11 |
| MOT test number | 626483135091 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
6 August 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 October |
| Days left | 155 |
| MOT expiry date | 6 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 8 |
| First mileage registration | 2018-06-30 |
| Last registration | 2023-08-07 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-06-30 | 10 mi |
| Registration #2 | 2021-06-08 | 21.356 mi |
| Registration #3 | 2022-01-12 | 24.082 mi |
| Registration #4 | | |
| Registration #5 | | |
| Registration #6 | | |
| Registration #7 | | |
| Registration #8 | | |

More info >



Safety ratings

| | | |
|----------------|---------------------------------|---|
| NCAP rating | ★★★★☆ | ▢ |
| Adult | 82% | |
| Children | 79% | |
| Pedestrian | 80% | |
| Safety systems | 56% | |
| Overall rating | 76% | |
| Video | see crash video | |

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1729 mm |
| Height | 1480 mm |
| Length | 4157 mm |
| Wheel base | 2595 mm |
| Kerb weight | 1008 kg |
| Max. allowed weight | 1510 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | B2170450372 |