



RENAULT



DUI4GOC

report date: 2024-03-28

General information

Make	RENAULT
Model	ZOE DYNAMIQUE INTENS
Colour	White
Year of manufacture	-
Top speed	84 mph
0 - 60 mph	13.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	87 BHP
Max. torque	220 Nm at 2.500 rpm
Fuel type	Electric



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-12
Pictures	1
Listing price	<a href="#">View report</a>



source: yesauto.com

**MOT history**

<b>MOT #7</b>	2021-03-26 16:38
<b>MOT test number</b>	685443675970
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-03-25
<b>Advice</b>	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #6</b>	2021-03-24 16:53
<b>MOT test number</b>	973355058623
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
<b>Advice</b>	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Offside Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
<b>Fail</b>	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

<b>MOT #5</b>	2019-12-20 11:03
<b>MOT test number</b>	840805851542
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing perishing outer sidewall (5.2.3 (d) (ii))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing perishing outer sidewall (5.2.3 (d) (ii))

<b>MOT #4</b>	2018-12-10 13:24
<b>MOT test number</b>	251526153543
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front tyre excess wear inner edge



MOT #3	2018-01-05 06:36
MOT test number	166829014223
Result	✓ Passed

MOT #2	2017-07-24 11:34
MOT test number	202449738212
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #1	2017-07-24 11:34
MOT test number	143760982387
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Rear registration plate has a feature which changes the appearance or legibility of the characters (6.3.4c)
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-07-30
Last registration	2021-03-26
Complete history	<a href="#">See info</a>



Registration #1	2014-07-30	19 mi
Registration #2	2017-07-24	23.285 mi
Registration #3	2017-07-24	23.285 mi
Registration #4	2018-01-05	26.877 mi
Registration #5	2018-12-10	33.241 mi
Registration #6	2019-05-20	35.277 mi
Registration #7	2019-05-20	35.277 mi
Registration #8	2019-05-20	35.277 mi
Registration #9	2021-03-26	35.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1468 kg
Max. allowed weight	1943 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	A052872
---------------	---------