



report date: 2024-03-29

General information

Make	SUZUKI
Model	SX4 SZ3
Colour	White
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	156 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	141 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-01-21
Pictures	7
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-26
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	19
Total items failed	10

MOT #13 2024-03-11 14:50

MOT test number 904326806381

Result ✓ Passed

Next expiry date 2025-03-26

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge EDGE 4MM (5.2.3 (e))

MOT #12 2024-03-11 11:58

MOT test number 846523506430

Result ✗ Failed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge EDGE 4MM (5.2.3 (e))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #11** 2023-03-27 14:14**MOT test number** 534713038677**Result** ✓ Passed**MOT #10** 2023-03-16 14:41**MOT test number** 300939991670**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2021-09-09 09:56**MOT test number** 750735959228**Result** ✓ Passed**MOT #8** 2020-10-02 13:55**MOT test number** 365617268055**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #7**

2020-09-25 13:17

MOT test number

419918510268

Result**✗ Failed****Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #6**

2019-10-08 13:17

MOT test number

395921419395

Result**✓ Passed****Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Brake pipe corroded, covered in grease or other material both front slightly corroded (1.1.11 (c))**MOT #5**

2019-10-08 11:03

MOT test number

923157238064

Result**✗ Failed****Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Brake pipe corroded, covered in grease or other material both front slightly corroded (1.1.11 (c))**MOT #4**

2018-10-04 11:26

MOT test number

115492797106

Result**✓ Passed****Advice** Windscreen chipped

**MOT #3** 2017-10-02 11:27**MOT test number** 348973261199**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #2** 2017-10-02 10:14**MOT test number** 281924900724**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2016-09-08 11:54**MOT test number** 662394367871**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
26 March 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	26 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-01
Last registration	2024-03-11
Complete history	See info



Registration #1	2013-09-01	9 mi
Registration #2	2016-09-08	22.327 mi
Registration #3	2017-10-02	24.907 mi
Registration #4	2017-10-02	24.907 mi
Registration #5	2018-10-04	27.221 mi
Registration #6	2019-10-08	29.069 mi
Registration #7	2019-10-08	29.069 mi
Registration #8	2020-09-25	30.732 mi
Registration #9	2020-09-25	30.732 mi
Registration #10	2020-09-25	30.732 mi
Registration #11	2020-09-25	30.732 mi
Registration #12	2020-09-25	30.732 mi
Registration #13	2020-09-25	30.732 mi
Registration #14	2020-09-25	30.732 mi
Registration #15	2020-09-25	30.732 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1620 mm
Length	4235 mm
Wheel base	2500 mm
Kerb weight	1240 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	M16A-1674084