



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Red
Year of manufacture	-
Top speed	100 mph
0 - 60 mph	14.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	81 BHP
Max. torque	116 Nm at 3.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.2 mpg







LABEL UNKNOWN



Internet history

Entry 2





Date	2021-09-14
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-30
Pictures	8
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #23	2021-10-08 13:25
MOT test number	601006393130
Result	✓ Passed
Next expiry date	2022-10-07
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #22	2021-10-07 11:57
MOT test number	501280234584
Result	✗ Failed
Fail	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Rear tyres are perished x 2
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Fail	Offside Headlamp aim too high (4.1.2 (a))
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #21	2020-09-26 15:29
MOT test number	439217779964
Result	✓ Passed

MOT #20	2019-09-23 09:48
MOT test number	826107464488
Result	✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
(5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
(5.3.4 (a) (i))

**MOT #19**

2019-09-23 09:05

MOT test number

922467794325

Result**✗ Failed****Advice**

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail

Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #18

2018-09-20 11:51

MOT test number

481914587223

Result**✓ Passed****MOT #17**

2017-09-11 10:24

MOT test number

442055991450

Result**✓ Passed****MOT #16**

2017-09-11 10:24

MOT test number

644139374139

Result**✗ Failed****Pass with rectification**

Windscreen washer provides insufficient washer liquid (8.2.3)

Pass with rectification

Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #15

2016-09-07 12:02

MOT test number

336725321781

Result**✓ Passed**

**MOT #14** 2015-09-08 10:43**MOT test number** 310323115074**Result** ✓ Passed**MOT #13** 2015-09-08 10:43**MOT test number** 837537023556**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively nearside and offside (8.2.2)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #12** 2014-09-12 15:34**MOT test number** 319685354253**Result** ✓ Passed**Notice** N/S/R tyre slightly perished.**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #11** 2014-09-12 12:47**MOT test number** 338205954423**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** N/S/R tyre slightly perished.**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #10** 2013-09-12 09:43**MOT test number** 245725253252**Result** ✓ Passed**MOT #9** 2012-09-18 13:55**MOT test number** 767432062210**Result** ✓ Passed**MOT #8** 2012-03-16 09:39**MOT test number** 589466672034**Result** ✓ Passed**Notice** Coolant leak**MOT #7** 2011-03-30 14:59**MOT test number** 189069781001**Result** ✓ Passed**Notice** O/s rear tyre perished,nail in it and down to 4.0mm tread**MOT #6** 2011-03-30 14:59**MOT test number** 285689481027**Result** ✗ Failed**Notice** O/s rear tyre perished,nail in it and down to 4.0mm tread**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #5** 2010-03-19 11:48**MOT test number** 381078670011**Result** ✓ Passed



MOT #4	2009-10-09 10:02
MOT test number	950052089299
Result	✓ Passed
MOT #3	2008-10-21 13:54
MOT test number	540145698202
Result	✓ Passed
MOT #2	2008-09-16 14:54
MOT test number	444580268252
Result	✓ Passed
MOT #1	2008-09-16 13:53
MOT test number	642240168270
Result	✗ Failed
Fail	Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2023-03-28
Current registration	XXXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-09-30
Last registration	2021-10-08
Complete history	See info



Registration #1	2005-09-30	28 mi
Registration #2	2008-09-16	29.205 mi
Registration #3	2008-09-16	29.205 mi
Registration #4	2008-10-21	29.588 mi
Registration #5	2009-10-09	33.263 mi
Registration #6	2010-03-19	36.183 mi
Registration #7	2011-03-30	55.101 mi
Registration #8	2012-03-16	69.477 mi
Registration #9	2012-09-18	73.649 mi
Registration #10	2013-09-12	76.586 mi
Registration #11	2014-09-12	79.927 mi
Registration #12	2014-09-12	79.927 mi
Registration #13	2015-09-08	85.494 mi
Registration #14	2016-09-08	91.061 mi
Registration #15	2017-09-08	96.628 mi
Registration #16	2018-09-08	102.195 mi
Registration #17	2019-09-08	107.762 mi
Registration #18	2020-09-08	113.329 mi
Registration #19	2021-09-08	118.896 mi
Registration #20	2022-09-08	124.463 mi
Registration #21	2023-09-08	130.030 mi
Registration #22	2024-09-08	135.597 mi
Registration #23	2025-09-08	141.164 mi
Registration #24	2026-09-08	146.731 mi
Registration #25	2027-09-08	152.298 mi



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1124 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4EA5801186