





report date: 2024-03-28

General information

| Make | MINI |
|---------------------|---------------------|
| Model | COOPER COOPER SEVEN |
| Colour | Grey |
| Year of manufacture | 2018 |
| Top speed | 130 mph |
| 0 - 60 mph | 7.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 134 BHP |
|-------------------------|---------------------|
| Max. torque | 220 Nm at 1.250 rpm |
| Engine capacity | 1.499 сс |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 48.7 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 107 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-20

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-04-07 |
|--------------------|------------|
| MOT pass rate | 57 % |
| MOT passed | 4 |
| Failed MOT tests | 3 |
| Total advice items | 6 |
| Total items failed | 2 |

| MOT #7 | 2024-04-05 14:19 |
|------------------|------------------|
| MOT test number | 705648574631 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-07 |

| MOT #6 | | 2024-04-04 12:26 |
|-----------------|---|------------------|
| MOT test number | er | 533424227080 |
| Result | | × Failed |
| DANGEROUS | Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |

| MOT #5 | 2023-04-05 15:05 |
|---|------------------|
| MOT test number | 468024839141 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #4 | | 2023-04-04 13:05 |
|----------|--|------------------|
| MOT test | number | 416340392774 |
| Result | | X Failed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| MAJOR | Windscreen washer not working (3.5 (a)) | |

CarCheck.co.uk page 3/11



report date: 2024-03-28

2022-04-08 11:45 **MOT #3** 795549491049 **MOT test number** Result ✓ Passed MOT #2 2022-04-08 11:45 **MOT** test number 876706380777 Result × Failed **Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT test number

Salant Salant

CarCheck.co.uk page 4/11



EK18XBC report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 94 |
| MOT expiry date | 7 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report I | |
|---|-------------|
| | |
| | |
| | |
| ************************************** | |
| *************************************** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | |
| Current registration | NK SIE |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



EK18XBC report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2018-03-31 |
| Last registration | 2024-04-05 |
| Complete history | See info |



| Registration #1 | 2018-03-31 | 25 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-03-26 | 43.165 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | 2022-04-08 | 50.150 mi |
| Registration #5 | 2022-04-08 | 50.150 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | D.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 73% |
| Pedestrian | 66% |
| Safety systems | 56% |
| Overall rating | 71% |
| Video | see crash video |



Dimensions & weight

| Width | 1727 mm |
|---------------------|---------|
| Height | 1414 mm |
| Length | 3821 mm |
| Wheel base | 2495 mm |
| Kerb weight | 1160 kg |
| Max. allowed weight | 1565 kg |

Additional information

| Fuel tank capacity | 40 | |
|-----------------------------------|------------------|-------|
| Fuel delivery | Direct Injection | |
| Number of doors | 3 | |
| Number of seats CarCheck.co.uk | 4 page | 11/11 |

Number of axles2Engine number32945140