



report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER HARD TOP
Colour	Blue
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.2 mpg
Consumption extra urban	32.8 mpg
Consumption combined	27.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-01
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-02-13
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	18
Total items failed	16

MOT #13 2023-02-14 17:05

MOT test number 607551852997

Result ✓ Passed

Next expiry date 2024-02-13

Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Rear Vehicle structure slightly corroded within 30cm of towbar mounting (6.1.6 (i) (i))

MOT #12 2021-12-20 13:51

MOT test number 683786120296

Result ✓ Passed

Advice Underside coated in wax oil restricting full inspection of body suspension and brake pipes

Advice Manufactures engine and body covers fitted restricting full inspection

MOT #11 2021-07-06 15:47

MOT test number 452434891761

Result ✓ Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2021-07-05 08:37

MOT test number

251283329276

Result

✗ Failed

- Fail** Brake performance not tested Brake pipe failure unsafe to test (1.2.1 (g))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Fail** Offside Front Brake pipe excessively corroded Short pipe on brake caliper (1.1.11 (c))
- Fail** Offside Front Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))
- Fail** Offside Rear Vehicle structure excessively corroded within 30cm of towbar mounting (6.1.6 (i) (i))
- Fail** Offside Rear Brake pipe excessively corroded Across axle (1.1.11 (c))
- Fail** Brake fluid contaminated (1.8 (a))
- Fail** Nearside Rear reflector missing (4.8.2 (a) (ii))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Front Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))
- Fail** Nearside Rear Vehicle structure excessively corroded within 30cm of towbar mounting (6.1.6 (i) (i))
- Fail** Nearside Rear Brake pipe excessively corroded Across axle (1.1.11 (c))
- Fail** Central Rear Suspension arm ball joint excessively worn Above rear axle (5.3.4 (a) (i))
- Fail** Offside Rear Brake pipe excessively corroded Front to rear pipe (1.1.11 (c))

MOT #9

2020-07-27 11:10

MOT test number

950831822510

Result

✓ Passed

- Advice** Underside covered in wax oil restricting full inspection
- Advice** Brake pipes have a protective coating I.e grease/underseal, restricting inspection of brake pipes.
- Advice** Manufactures engine and body covers fitted restricting full inspection

**MOT #8**

2019-06-12 09:37

MOT test number

290433222641

Result

✓ Passed

Advice Brake pipes have a protective coating I.e grease/underseal, restricting inspection of brake pipes.**Advice** Suspension component mounting prescribed area is corroded but not considered excessive
nearside front and rear offside front and rear (5.3.6 (a) (i))**Advice** Underside of vehicle covered in wax oil restricting full inspection**MOT #7**

2018-06-18 12:19

MOT test number

544302161839

Result

✓ Passed

Advice Underside of vehicle covered in protective coating I.e underseal, restricting inspection**Advice** Nearside Front Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))**Advice** Brake pipes have a protective coating I.e grease/underseal, restricting inspection of brake pipes.**Advice** Offside Front Brake pipe corroded, covered in grease or other material from flexi to caliper (1.1.11 (c))**MOT #6**

2017-06-27 11:13

MOT test number

680911847730

Result

✓ Passed

Advice Brake pipes have a protective coating I.e grease/underseal, restricting inspection of brake pipes.**Advice** Underside of vehicle covered in protective coating I.e underseal, restricting inspection.**MOT #5**

2016-06-28 11:07

MOT test number

666273254483

Result

✓ Passed

MOT #4

2015-06-30 11:32

MOT test number

325621285143

Result

✓ Passed



MOT #3	2014-07-04 10:21
MOT test number	129545884121
Result	✓ Passed
MOT #2	2013-04-09 10:21
MOT test number	287299493074
Result	✓ Passed
MOT #1	2013-04-09 10:21
MOT test number	726309293018
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Pass with rectification	Offside Headlamp aim too far to the right (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✗
MOT
Expired:
13 February 2024

Tax status		Valid until 1 February
Days left		278
MOT expiry date		13 February 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	CV10FXJ
Plate since	2019-03-28
Current registration	CV10FXJ
Plate since	2019-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-03-04
Last registration	2023-02-14
Complete history	See info



Registration #1	2010-03-04	23 mi
Registration #2	2013-04-09	33.758 mi
Registration #3	2014-07-04	38.223 mi
Registration #4	2015-06-30	42.217 mi
Registration #5	2016-06-28	45.920 mi
Registration #6	2017-06-27	49.332 mi
Registration #7	2018-06-18	52.851 mi
Registration #8	2019-06-20	55.277 mi
Registration #9	2020-06-20	57.277 mi
Registration #10	2021-06-20	59.277 mi
Registration #11	2022-06-20	61.277 mi
Registration #12	2023-06-20	63.277 mi
Registration #13	2024-06-20	65.277 mi
Registration #14	2025-06-20	67.277 mi

More info >



Dimensions & weight

Width	1790 mm
Height	1968 mm
Length	3649 mm
Kerb weight	1750 kg
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Number of axles	2
Engine number	100604011809244DT