

Ford



General information

Make	FORD
Model	TRANSIT 350 TREND H/R P/V
Colour	Black
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	350 Nm at 2.400 rpm
Engine capacity	2.198 сс
Cylinders	4
Fuel type	Diesel





MOT history

MOT expiry date	2024-12-07
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	20
Total items failed	5

МОТ #9	2023-12-08 14:43
MOT test number	540138013454
Result	✓ Passed
Next expiry date	2024-12-07

MOT #8	2022-11-10 09:19
MOT test number	473690855182
Result	✓ Passed

МОТ #7	2021-11-24 15:46
MOT test number	237761639620
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in exce (5.3.4 (a) (i))	essive movement rear bush
Advice Nearside Front Suspension arm pin or bush worn but not resulting in exbush (5.3.4 (a) (i))	ccessive movement rear



M	1	F	5	9	D	Ζ	Κ
	re	po	rt d	ate	: 20	24-0	3-28

MOT #6		2017-11-28 09:14
MOT test n	umber	849930945414
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #5		2016-12-01 16:29
MOT test n	umber	552274582527

Result		✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Rear Brake pad(s) wearing thin inner (3.5.1g)	
Advice movemen	Nearside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive t (D) bush (2.4.G.2)	
Advice	Central Front Seat belt stitching slightly frayed (5.2.2b)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Rear Brake pad(s) wearing thin inner (3.5.1g)	
Advice (D) bush (Offside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive mo 2.4.G.2)	ovement





MOT #4	2016-12-01 10:02
MOT test number	720005491505
Result	🗙 Failed
Advice Offside Front Anti-roll bar rubber mounting deteriorated but not resulting in e (D) bush (2.4.G.2)	xcessive movement
FailDriver's seat insecure frame snapped/broken (6.2.A.1)	
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened	(3.5.1i)
Advice Nearside Rear Brake pad(s) wearing thin inner (3.5.1g)	
Advice Nearside Front Anti-roll bar rubber mounting deteriorated but not resulting in movement (D) bush (2.4.G.2)	excessive
FailBrake pedal anti-slip provision incomplete (3.3.A.1b)	
Advice Central Front Seat belt stitching slightly frayed (5.2.2b)	
Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3	3.5.1i)
Advice Offside Rear Brake pad(s) wearing thin inner (3.5.1g)	
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	

MOT #3	2015-11-30 15:34
MOT test number	863705727353
Result	✓ Passed

MOT #2	2015-11-30 15:25
MOT test number	404802025005
Result	× Failed
Fail Offside Rear Rear fog lamp not working (1.3.2b)	
Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)	

MOT #1	2014-12-01 16:16
MOT test number	497195234338
Result	✓ Passed



MF59DZK report date: 2024-03-28

Tax & MOT check

√ Taxed	✓ MOT
Tax due: 1 April 2025	Expires: 7 December 2024
Tax status	Valid until 1 April
Days left	337
MOT expiry date	7 December 2024
Full MOT history	See MOT history





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2010-02-01
Last registration	2023-12-08
Complete history	<u>See info</u>



Registration #1	2010-02-01	13 mi
Registration #2	2014-12-01	70.926 mi
Registration #3	2015-11-30	73.184 mi
Registration #4	2015-11-30	73.184 mi
Registration #5	2016-12-01	74.741 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		

More info >





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	2374 mm
Height	2543 mm
Length	5680 mm
Kerb weight	1873 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	AB29293