




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Silver
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg
CO2 emission	185 g/km
CO2 label	I





## Internet history

### Entry 2


Date	2021-11-01
Pictures	15
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

### Entry 1

Date	2021-10-04
Pictures	15
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-08
MOT pass rate	55 %
MOT passed	11
Failed MOT tests	9
Total advice items	26
Total items failed	20

MOT #20 2023-10-09 13:06

MOT test number 344808156061

Result ✔ Passed

Next expiry date 2024-10-08

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Coolant leak

MOT #19 2023-10-09 13:06

MOT test number 758665169678

Result ✘ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Coolant leak
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))



**MOT #18** 2022-09-08 14:38

**MOT test number** 153727462177

**Result** ✔ Passed

**Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))

**MOT #17** 2022-09-08 09:24

**MOT test number** 408559981104

**Result** ✘ Failed

**Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))

**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #16** 2021-10-01 14:41

**MOT test number** 766685960766

**Result** ✔ Passed

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #15** 2020-12-18 09:17

**MOT test number** 809909694004

**Result** ✔ Passed

**MOT #14** 2019-05-30 13:07

**MOT test number** 382480860874

**Result** ✔ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



<b>MOT #13</b>	2019-05-30 13:07
<b>MOT test number</b>	341686811149
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Front Headlamp aim too low (4.1.2 (a))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Pass with rectification</b>	Nearside Front Headlamp aim too low (4.1.2 (a))

<b>MOT #12</b>	2018-06-04 18:38
<b>MOT test number</b>	565550574905
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front head light lens damaged

<b>MOT #11</b>	2018-06-04 12:11
<b>MOT test number</b>	125052217375
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Position lamp not working (4.2.1 (a))
<b>Advice</b>	Nearside Front head light lens damaged
<b>Fail</b>	Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
<b>Fail</b>	Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))
<b>Fail</b>	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
<b>Fail</b>	Offside Rear Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

<b>MOT #10</b>	2017-05-09 16:08
<b>MOT test number</b>	710618317495
<b>Result</b>	✓ Passed



MOT #9 2017-05-08 15:28

MOT test number 360350830693

Result ✗ Failed

- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Nearside Front Suspension arm rubber mounting bonding deteriorated resulting in excessive movement wishbone rear bush (2.4.G.2)
- Fail** Offside Headlamp aim too low (1.8)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Suspension arm rubber mounting bonding deteriorated resulting in excessive movement wishbone rear bush (2.4.G.2)
- Fail** Windscreen wiper does not clear the windscreen effectively both (8.2.2)

MOT #8 2015-06-24 17:14

MOT test number 247335175409

Result ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Nail in offside rear tyre
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #7 2015-06-24 16:31

MOT test number 445135375139

Result ✗ Failed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nail in offside rear tyre



**MOT #6** 2013-06-04 16:22

**MOT test number** 877025153194

**Result** ✓ Passed

**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2013-06-04 10:25

**MOT test number** 567655353111

**Result** ✗ Failed

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2012-03-07 16:58

**MOT test number** 129997362440

**Result** ✓ Passed

**MOT #3** 2012-03-07 14:10

**MOT test number** 789157262092

**Result** ✗ Failed

**Notice** Both front tyres wearing on inner edges

**Fail** Parking brake lever is fouling adjacent parts of the vehicle (3.1.6b)

**MOT #2** 2010-08-18 11:33

**MOT test number** 913580830281

**Result** ✓ Passed



**MOT #1** 2010-08-18 10:18

**MOT test number** 770730830223

**Result** ✗ Failed

**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 November 2024

✓  
**MOT**

**Expires:**  
8 October 2024

**Tax status** Valid until 1 November

**Days left** 186

**MOT expiry date** 8 October 2024

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>VO57GDK</b>
Plate since	2019-09-29
Current registration	<b>VO57GDK</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.
If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.
Download the premium report here and check if this VOLKSWAGEN is financed.


Table with 2 columns: Finance company, Date of agreement, Agreement type, Agreement term, Agreement number, Contact info. All cells are redacted.

More info >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	23
<b>First mileage registration</b>	2007-09-01
<b>Last registration</b>	2023-10-09
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2007-09-01	7 mi
<b>Registration #2</b>	2010-08-18	21.595 mi
<b>Registration #3</b>	2010-08-18	21.595 mi
<b>Registration #4</b>	2012-03-07	32.307 mi
<b>Registration #5</b>	2012-03-07	32.310 mi
<b>Registration #6</b>	2013-06-04	47.620 mi
<b>Registration #7</b>	2013-06-04	47.630 mi
<b>Registration #8</b>	2015-06-24	65.455 mi
<b>Registration #9</b>	2015-06-24	65.455 mi
<b>Registration #10</b>	2017-05-08	77.407 mi
<b>Registration #11</b>	2017-05-09	77.410 mi
<b>Registration #12</b>	2018-06-04	84.747 mi
<b>Registration #13</b>	2019-06-04	92.084 mi
<b>Registration #14</b>	2019-06-04	92.084 mi
<b>Registration #15</b>	2019-06-04	92.084 mi
<b>Registration #16</b>	2019-06-04	92.084 mi
<b>Registration #17</b>	2019-06-04	92.084 mi
<b>Registration #18</b>	2019-06-04	92.084 mi
<b>Registration #19</b>	2019-06-04	92.084 mi
<b>Registration #20</b>	2019-06-04	92.084 mi
<b>Registration #21</b>	2019-06-04	92.084 mi
<b>Registration #22</b>	2019-06-04	92.084 mi
<b>Registration #23</b>	2023-10-09	100.000 mi

[More info >](#)



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1393 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2

---

<b>Number of seats</b>	4
<b>Number of axles</b>	2
<b>Engine number</b>	BFS 062004