



report date: 2024-03-28

General information

Make	JAGUAR
Model	XK V8 SOVEREIGN
Colour	Green
Year of manufacture	2008
Top speed	155 mph
0 - 60 mph	6.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	300 BHP
Max. torque	420 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.9 mpg
Consumption extra urban	33.8 mpg
Consumption combined	24.8 mpg
CO2 emission	269 g/km
CO2 label	M





Internet history

Entry 2

Date	2021-07-26
Pictures	18
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-24
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-18
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	13
Total items failed	7

MOT #19	2024-01-23 14:11
MOT test number	861655195217
Result	✓ Passed
Next expiry date	2025-02-18

MOT #18	2024-01-22 09:43
MOT test number	582903402959
Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear exhaust heat shield insecure
Fail	Offside Rear Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
Fail	Nearside Rear Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing outer side wall (5.2.3 (d) (ii))

**MOT #17** 2023-01-19 09:42**MOT test number** 523462628154**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Rear Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Rear Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #16** 2022-02-16 16:36**MOT test number** 572800400718**Result** ✓ Passed**MOT #15** 2022-02-16 16:36**MOT test number** 750635572387**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #14** 2021-02-15 10:38**MOT test number** 761228340223**Result** ✓ Passed**MOT #13** 2020-02-12 15:42**MOT test number** 719025109264**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2020-02-07 12:01**MOT test number** 478830327424**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #11** 2019-02-15 11:58**MOT test number** 738331816624**Result** ✓ Passed**MOT #10** 2018-02-15 09:16**MOT test number** 157780316381**Result** ✓ Passed**MOT #9** 2017-01-31 16:48**MOT test number** 312412627040**Result** ✓ Passed**MOT #8** 2016-02-10 16:07**MOT test number** 816365653278**Result** ✓ Passed**MOT #7** 2016-02-09 09:29**MOT test number** 359175705705**Result** ✗ Failed**Fail** Offside Front Headlamp adversely affected by the operation of another lamp (1.7.5c)**Advice** Nearside Rear tyre cuts to outer side wall no cords shown**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer side wall (4.1.D.1a)

**MOT #6** 2015-02-09 12:39**MOT test number** 748630745064**Result** ✓ Passed**MOT #5** 2014-02-14 10:55**MOT test number** 447115944027**Result** ✓ Passed**MOT #4** 2013-02-19 10:28**MOT test number** 256820153028**Result** ✓ Passed**MOT #3** 2012-09-28 10:56**MOT test number** 559752272235**Result** ✓ Passed**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Road wheel slightly damaged (4.2.A.1a)**MOT #2** 2011-09-26 17:43**MOT test number** 108969161276**Result** ✓ Passed**MOT #1** 2011-09-26 13:16**MOT test number** 308149361447**Result** ✗ Failed**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	YH58RZT
Plate since	2019-09-28
Current registration	YH58RZT
Plate since	2019-09-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-10-03
Last registration	2024-01-23
Complete history	See info



Registration #1	2008-10-03	18 mi
Registration #2	2011-09-26	19.432 mi
Registration #3	2011-09-26	19.342 mi
Registration #4	2012-09-28	24.914 mi
Registration #5	2013-02-19	26.372 mi
Registration #6	2014-02-14	29.139 mi
Registration #7	2015-02-09	31.116 mi
Registration #8	2016-02-09	36.034 mi
Registration #9	2016-02-10	36.035 mi
Registration #10	2017-01-31	38.874 mi
Registration #11	2018-02-15	40.260 mi
Registration #12	2019-05-29	51.277 mi
Registration #13	2019-05-29	51.277 mi
Registration #14	2019-05-29	51.277 mi
Registration #15	2019-05-29	51.277 mi
Registration #16	2019-05-29	51.277 mi
Registration #17	2019-05-29	51.277 mi
Registration #18	2019-05-29	51.277 mi
Registration #19	2019-05-29	51.277 mi
Registration #20	2019-05-29	51.277 mi
Registration #21	2019-05-29	51.277 mi
Registration #22	2019-05-29	51.277 mi

More info >



Dimensions & weight

Width	2104 mm
Height	1462 mm
Length	5091 mm
Wheel base	3034 mm
Max. allowed weight	2223 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	07120322185G