



report date: 2024-03-29

General information

Make	FORD
Model	FIESTA STYLE PLUS TDCI
Colour	Blue
Year of manufacture	2010
Top speed	101 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	B





MOT history

MOT expiry date	2023-04-10
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	21
Total items failed	5

MOT #13	2022-04-11 19:09
MOT test number	718369859662
Result	✓ Passed
Next expiry date	2023-04-10

MOT #12	2020-12-09 14:56
MOT test number	336018075036
Result	✓ Passed

MOT #11	2019-12-02 16:49
MOT test number	326810402763
Result	✓ Passed

MOT #10	2019-12-02 15:01
MOT test number	407006860339
Result	✗ Failed

Fail

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #9**

2019-01-28 10:52

**MOT test number**

685158655586

**Result**

✓ Passed

- Advice** Nearside Front tyre was low = requires rechecking
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside mirror assembly damaged
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #8**

2018-01-24 14:42

**MOT test number**

376241366949

**Result**

✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Rear heat shield insecure
- Advice** Rear silencer split and corroded
- Advice** Under covers fitted

**MOT #7**

2018-01-24 11:09

**MOT test number**

411618376214

**Result**

✗ Failed

- Advice** Rear silencer split and corroded
- Advice** Under covers fitted
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Advice** Rear heat shield insecure
- Advice** Items removed from driver's view prior to test
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)

**MOT #6** 2017-01-27 14:38**MOT test number** 374781539609**Result** ✓ Passed**MOT #5** 2016-02-08 16:09**MOT test number** 192260653332**Result** ✓ Passed

- Advice** Back box outer shell has slight corrosion
- Advice** Rear brake fluctuating, but not excessively (3.7.B.3)
- Advice** Oil leak onto flexi exhaust, oil level getting low
- Advice** Nearside Front Tyre worn close to the legal limit under 3mm, bald on inner edge, 195/50/15v (4.1.E.1)

**MOT #4** 2016-02-05 15:52**MOT test number** 107374284404**Result** ✗ Failed

- Fail** Nearside Front Front wheel bearing has excessive play (2.5.A.3c)

**MOT #3** 2015-01-20 15:11**MOT test number** 968160225083**Result** ✓ Passed**MOT #2** 2014-02-07 11:06**MOT test number** 675878234026**Result** ✓ Passed



MOT #12013-01-07 11:23

MOT test number348467703064

Result

✓ Passed

- Advice

Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice

Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>MM59JJV</b>
Plate since	2019-03-29
Current registration	<b>MM59JJV</b>
Plate since	2019-03-29

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-02-24
Last registration	2022-04-11
Complete history	<a href="#">See info</a>



Registration #1	2010-02-24	6 mi
Registration #2	2013-01-07	25.141 mi
Registration #3	2014-02-07	28.148 mi
Registration #4	2015-01-20	30.188 mi
Registration #5	2016-02-05	35.096 mi
Registration #6	2016-02-08	35.138 mi
Registration #7	2017-01-27	42.310 mi
Registration #8	2018-01-27	50.277 mi
Registration #9	2019-01-27	58.244 mi
Registration #10	2020-01-27	66.211 mi
Registration #11	2021-01-27	74.178 mi
Registration #12	2022-01-27	82.145 mi
Registration #13	2023-01-27	90.112 mi
Registration #14	2024-01-27	98.079 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Kerb weight	1141 kg
Max. allowed weight	1535 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2

**Engine number**

9R21853