





### General information

Make	CITROEN
Model	C4 PICASSO BLUEHDI EXCLUSIVE
Colour	Grey
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	100 g/km
CO2 label	A







### Internet history

Entry 2

Date Pictures 2022-08-12

41

Listing price

View report



source: cargurus.co.uk

Entry 1	
Date	2022-01-21
Pictures	1
Listing price	View report



source: cargurus.co.uk



# MOT history

MOT expiry date	2024-09-01
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	5
Total items failed	5

МОТ #9	2023-08-30 15:56
MOT test number	926341952278
Result	✓ Passed
Next expiry date	2024-09-01

MOT #8	2022-09-02 12:36
MOT test number	511542404279
Result	✓ Passed

MOT #7	2021-12-07 17:00
MOT test number	336582428210
Result	✓ Passed

MOT #6	2021-12-07 12:17
MOT test number	574507224107
Result	🗙 Failed
Fail Nearside Side repeater not working (4.4.1 (a) (ii))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	1
Advice Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	





MOT #5	2020-12-16 13:41
MOT test number	879080598091
Result	✓ Passed
MOT #4	2020-12-16 13:41
MOT test number	910499218180
Result	× Failed
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))
<b>Pass with rectification</b> Front Windscreen washer provides insufficient washer liquid (3.5 (a))	

MOT #3	2019-12-17 16:02
MOT test number	713137329008
Result	✓ Passed

MOT #2	2019-07-17 14:14
MOT test number	945746149779
Result	✓ Passed

MOT #1	2019-07-17 13:14	
MOT test number	494298353250	
Result	🗙 Failed	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
FailOffside Rear Outer Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d)(ii))		
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Fail Nearside Rear Outer Tyre has ply or cords exposed (5.2.3 (d) (ii))		



Tax & MOT check

√ Taxed	√ МОТ
<b>Tax due:</b> 1 September 2024	Expires: 1 September 2024
Tax status	Valid until 1 September
Days left	125
MOT expiry date	1 September 2024
Full MOT history	See MOT history
Tax calculation	
Vehicle class	40

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Law P
Туре	
Damage 2	AMPLE
Damage 2	E CAT D
Date	 *
Category	 AMPT
Туре	

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





# Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
***********	
*******	
******	
**********	
********	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-05-18
Last registration	2023-08-30
Complete history	<u>See info</u>



Registration #1	2016-05-18	16 mi
Registration #2	2019-07-17	23.497 mi
Registration #3	2019-07-17	23.497 mi
Registration #4	2019-12-17	26.855 mi
Registration #5	2020-12-16	40.462 mi
Registration #6	2020-12-16	40.462 mi
Registration #7		11.777 esi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		

More info >





# Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1826 mm
Height	1610 mm
Length	4428 mm
Wheel base	2785 mm
Kerb weight	1320 kg
Max. allowed weight	1950 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	JBGY0067122