





report date: 2024-03-28

General information

Make	PEUGEOT
Model	106 INDEPENDENCE
Colour	Silver
Year of manufacture	-
Top speed	101 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	89 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-10-21

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT #20 2021-06-05 09:01

MOT test number 926806349812

Next expiry date 2022-06-04

MOT #19 2021-06-02 13:47

MOT test number 101961718431

Result X Failed

Fail Front Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #18 2020-06-05 10:36

MOT test number 350636792335

Advice Offside Front noise from wheel when rotated on full lock

Advice Side repeater slightly discoloured n/s and o/s (4.4.3 (a))

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

Advice Coolant leak radiator cap faulty

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge tyre size (165/65/13) (5.2.3 (e))

MOT #17 2019-06-07 13:26

MOT test number 490537997366

Result \(\sqrt{Passed} \)

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 3/12



MOT #16 2019-06-05 14:50

MOT test number 872219232033

Result X Failed

Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15 2018-06-08 10:08

MOT test number 116428362605

Result ✓ Passed

MOT #14 2017-06-01 09:58

MOT test number 292139645292

Result \rightarrow Passed

MOT #13 2017-06-01 09:58

MOT test number 389077457226

Result X Failed

Pass with rectification Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #12 2016-06-08 09:48

MOT test number 652466674743

Result \rightarrow Passed

CarCheck.co.uk page 4/12



MOT #11 2015-06-05 10:53

MOT test number 895666955159

Notice Exhaust rubber missing mid section

Notice Offside front tyre perrished

Notice Vehicle's internal headlight adjuster altered to recheck lights

Notice Nearside rear tyre perrished

MOT #10 2014-06-09 15:19

MOT test number 287430764485

Result \rightarrow Passed

Notice Corrosion on exhaust back box

MOT #9 2014-06-09 10:48

MOT test number 927590564115

Result × Failed

Fail Service brake: efficiency below requirements (3.7.B.7)

Notice Corrosion on exhaust back box

Fail Brakes imbalanced across an axle (3.7.B.5b)

MOT #8 2013-06-12 12:01

MOT test number 588053263136

MOT #7 2012-02-13 12:53

MOT test number 836714742026

CarCheck.co.uk page 5/12



MOT #6 2011-02-15 09:27 **MOT** test number 626276341012 ✓ Passed Result **Notice** O/S Door mirror slightly damage

Notice N/S/R tyre has slight side wall damage	
MOT #5	2010-02-23 11:54
MOT test number	434954050008
Result	✓ Passed
MOT #4	2009-02-26 10:00
MOT test number	443847859053
Result	✓ Passed
MOT #3	2008-02-25 12:19
MOT test number	534656558083
Result	✓ Passed
MOT #2	2007-02-20 11:48
MOT test number	391121257009
Result	✓ Passed
MOT #1	2006-02-14 11:55
MOT test number	453695546032
Result	✓ Passed

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		GEOT

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-03-01
Last registration	2021-06-05
Complete history	See info



Registration #1	2003-03-01	15 mi
Registration #2	2006-02-14	5.713 mi
Registration #3	2007-02-20	7.419 mi
Registration #4	2008-02-25	8.821 mi
Registration #5	2009-02-26	10.314 mi
Registration #6	2010-02-23	12.026 mi
Registration #7	2011-02-15	13.467 mi
Registration #8	2012-02-13	15.896 mi
Registration #9	2013-06-12	25.293 mi
Registration #10	2014-06-09	29.077 mi
Registration #11	2014-06-09	29.077 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.117 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		77,777 44

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

'			^	• 1	
	imensi	ione i	N. W.O.	ıaı	рΕ
		IUII 5 I	\mathbf{x} $\mathbf{v}\mathbf{v}\mathbf{c}$	IUI	

Width	1594 mm
Height	1357 mm
Length	3678 mm
Wheel base	2385 mm
Kerb weight	815 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Single-Point Injection
Number of doors	3
Number of axles	2
Engine number	FP6T4223351

CarCheck.co.uk page 12/12