



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 MILLESIM
Colour	Black
Year of manufacture	-
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #11</b>	2020-06-13 08:01
<b>MOT test number</b>	203735402004
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-06-22

<b>MOT #10</b>	2019-05-31 15:38
<b>MOT test number</b>	157075223963
<b>Result</b>	✓ Passed

<b>MOT #9</b>	2018-05-23 11:47
<b>MOT test number</b>	289099083046
<b>Result</b>	✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2018-05-22 11:12**MOT test number** 702637217120**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2017-06-12 13:49**MOT test number** 816492031750**Result** ✓ Passed**MOT #6** 2016-06-15 14:06**MOT test number** 453076668319**Result** ✓ Passed**MOT #5** 2016-06-15 14:06**MOT test number** 580501680050**Result** ✗ Failed**Pass with rectification** Exhaust system not adequately supported (7.1.1)

**MOT #4** 2015-06-17 09:51**MOT test number** 287868665400**Result** ✓ Passed**MOT #3** 2014-06-19 11:19**MOT test number** 936560574153**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2013-06-17 15:47**MOT test number** 216888463482**Result** ✓ Passed**MOT #1** 2013-06-17 10:25**MOT test number** 619818363171**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2010-06-22
Last registration	2020-06-13
Complete history	<a href="#">See info</a>



Registration #1	2010-06-22	21 mi
Registration #2	2013-06-17	38.629 mi
Registration #3	2013-06-17	38.629 mi
Registration #4	2014-06-19	57.900 mi
Registration #5	2015-06-17	75.404 mi
Registration #6	2016-06-15	88.303 mi
Registration #7	2019-06-20	95.277 mi
Registration #8	2019-06-20	95.277 mi
Registration #9	2019-06-20	95.277 mi
Registration #10	2019-06-20	95.277 mi
Registration #11	2019-06-20	95.277 mi
Registration #12	2019-06-20	95.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	865 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number

6589212